Cardona Solar Farm: Performance Report, Summer 2026

1 Summary

The Cardona solar farm has an installed capacity of 48 megawatts peak. The summer was sunnier than the ten-year average, but a transformer failure stopped one of the four blocks for eleven days.

2 Production

The monthly energy delivered to the grid is shown in the chart below.



Figure 1. Monthly energy delivered, in gigawatt-hours.

3 Availability

Availability is the share of the time during which the inverters were able to produce.



Figure 2. Monthly availability of the inverters, in percent.

The drop of one month is due to the transformer failure of block C, repaired with a spare unit.

4 Maintenance

The panels were cleaned twice, in May and in August. Vegetation under the rows was grazed by a flock of 320 sheep from a neighbouring farm instead of being mowed.