

INSPECTION REPORT

JOB CARD
J-00018

INSPECTED
9 Oct 2026, 09:45

APPROVED
9 Oct 2026, 10:45

TECHNICIAN
Tech One

CUSTOMER

V14 Quote Test

Mobile +971500000017

VEHICLE

Porsche Cayenne 2023


Plate Dubai C 99903
VIN WP0ZZZ99ZRS199903

YOUR REQUESTS

1. Brake noise **BAD**

Found: Front pads worn to the metal.



Needs: Replace front pads and discs



ITEMS NEEDING ATTENTION · 3

BAD Tyres + valve + valve cover Wheels, tyres and brakes
Rear right 2 mm.

BAD Brake pads Wheels, tyres and brakes
Front pads 2 mm.



AVERAGE Brake discs Wheels, tyres and brakes
Front discs scored.

FULL CHECKLIST

ENGINE BAY

GOOD Bonnet shocks + lever/cable
GOOD Engine covers
GOOD Engine oil cap

Prepared by Mert

This is a computer generated document which requires no stamp and signature.
This report describes the condition found at inspection. A quotation for any work follows separately.
Terms and conditions: erp.ofjauto.com/terms



GOOD	Engine oil level and condition
GOOD	Engine oil filter
GOOD	Engine air filter + housing/pipes/connector/hoses
GOOD	Serpentine belt + auxiliary belts
GOOD	Idler / tensioner / pulley
GOOD	Spark plugs
GOOD	Ignition coil + wiring
GOOD	Valve cover
GOOD	Wiper tank + pipes/connector/hoses + wiper blades
GOOD	Brake fluid
GOOD	Supercharger / turbo system + brake vacuum pump
GOOD	Engine oil cooler
GOOD	Transmission oil cooler
GOOD	Engine mounts
COOLING	
GOOD	Coolant tanks + pipes/connector/hoses + water pump + thermostat
GOOD	Radiator + pipes/connector/hoses
GOOD	Water pump + thermostat
OIL LEAKS	
GOOD	Engine top side
GOOD	Engine front side
GOOD	Engine mid/lower portion
GOOD	Engine rear side
TRANSMISSION AND DRIVELINE	
GOOD	Transmission mounts
GOOD	Transmission mechanical
GOOD	Transmission electrical
GOOD	Transfer case
GOOD	Drive shaft + aux shaft + bushings/coupler/bearing
GOOD	Differential bushes
GOOD	Front differential oil leak
GOOD	Rear differential
GOOD	Transmission and differential fluid condition
STEERING AND SUSPENSION	
GOOD	Shock mounts + connectors
GOOD	Power steering rack bushes/leak/play + boots + tie rod
GOOD	Stabilizer leak/bushes/electrical fault + link rod + stabilizer bar bush
GOOD	Lower arms
GOOD	Upper arms
GOOD	Front shock absorbers (air / hydraulic)
GOOD	Height level sensor

Prepared by **Mert**

This is a computer generated document which requires no stamp and signature.

This report describes the condition found at inspection. A quotation for any work follows separately.

Terms and conditions: erp.ofjauto.com/terms



GOOD Rear suspension arms/bushes

GOOD Rear shock absorbers

GOOD Wheel alignment

UNDERBODY

GOOD Undercovers + bolts/fasteners/clips

GOOD Exhaust + O2 sensor + catalyst

GOOD Fuel tank + cover

GOOD Fender liner

WHEELS, TYRES AND BRAKES

GOOD Wheel bearing

GOOD Wheel bolts

GOOD Wheel condition + centre cap

BAD Tyres + valve + valve cover

AVERAGE Brake discs

BAD Brake pads

GOOD Brake fluid pipes / caliper leak / piston jam

GOOD Brake dust cover

ELECTRICAL

GOOD Battery + aux battery

GOOD Front headlights

GOOD Rear tail lamps + brake light

GOOD Side view mirrors

GOOD Alternator / starter motor

GOOD Infotainment system

GOOD Parking sensors

GOOD Seats

GOOD Gear shifter

GOOD Parking brakes

GOOD Electric power steering

GOOD Tyre pressure sensor

GOOD Dashboard warning lights

GOOD Horn

GOOD Windows, sunroof and central locking

GOOD Interior lights

AIR CONDITIONING

GOOD A/C compressor / expansion valve / condenser / evaporator / pipes

GOOD Cabin filter

OTHER

GOOD Other

TYRES AND BRAKES

Prepared by Mert

This is a computer generated document which requires no stamp and signature.

This report describes the condition found at inspection. A quotation for any work follows separately.

Terms and conditions: erp.ofjauto.com/terms



Front left	6 mm · 2023	Good	None
Front right	6 mm · 2023	Good	None
Rear left	5 mm · 2023	Good	None
Rear right	2 mm · 2023	Worn out	Replace now
Front brake pads	2 mm		
Rear brake pads	7 mm		
Battery voltage	12.6 V		
Battery health	Good		
A/C vent temperature	7 °C		

ROAD TEST

BAD **Noises** Grinding when braking.

GOOD **Vibration**

GOOD **Pulling to one side**

GOOD **Gearbox behaviour**

GOOD **Braking**

WORKSHOP MANAGER'S NOTE

Checked.

Prepared by **Mert**

This is a computer generated document which requires no stamp and signature.

This report describes the condition found at inspection. A quotation for any work follows separately.

Terms and conditions: erp.ofjauto.com/terms

