FICTIONAL DEMONSTRATION — NO REAL CUSTOMER DATA

Palm Ridge Offices — Service Visit Closeout

Fictional work-order closeout with sample before-and-after results.

Work order	DEMO-24018
Asset	AHU-03
Status	Completed — simulated
Comfort result	72°F supply zone / stable

Reported issue

Second-floor west offices were represented as warmer than the target during a simulated afternoon load.

Work performed

The fictional technician inspected airflow, cleaned the simulated sensor, verified damper response and documented stable operation.

Closeout

No follow-up is required in this example. The customer may reopen or create another simulated service request in the portal.

Prepared for the O’Brien Elite Portal public demonstration. All names, assets, readings, dates, prices, documents and workflows in this file are fictional.