Reservoir monitoring report

This report summarises the monitoring campaign of the three reservoirs in the upper basin. Table 1 lists the stations and Table 2 the readings of the last quarter; both were checked against the field notebooks.

Table 1: Monitoring stations.

Station	Location	Started
North	Left bank, next to the old pumping house	2019
Centre	Dam crest	2020
South	Right bank, below the spillway and the access road	2021

Readings are taken every morning at the same hour. The level is given in metres above the reference datum and the flow in cubic metres per second.

Table 2: Quarterly readings.

Month	Level	Inflow	Outflow
January	412.6	18.4	15.2
February	413.1	21.7	16.9
March	414.0	25.3	19.8
April	414.8	27.1	22.4

Table 2 shows a steady rise of the level during the quarter, in line with the snowmelt expected for the season. No station reported a fault.