



Office Warehouse, Inc.

JRF No.

ECO-26-002

JOB REQUEST FORM

Requested by Princess Sanlitan
Branch/Department Ever Commonwealth

Date Requested
Monday, March 23, 2026

Please check box(es) ☐ for specific request

CARPENTRY - REPAIR/REPLACEMENT/CLEANING

- | | | |
|---|--|--|
| ☐ Repainting of Interior Wall | ☐ Repair of Wall crack | ☐ Replacement of Tiles/Flooring |
| ☐ Repainting of Counter Booth | ☐ Repair of Flooring (Tiles, Wood flooring) | ☐ Replacement of Counterbooth |
| ☐ Repainting of Window Display | ☐ Repair of Glass Cabinet | |
| ☐ Ceiling problem | ☐ Repair of Interior Wall | |
| ☐ Water leak | ☐ Repair of Storage Cabinet | |

ELECTRICAL - REPAIR/REPLACEMENT/CLEANING

- | | | |
|---|---|--|
| ☐ Repair of Lighting Fixture | ☐ Additional Lighting to be installed | ☐ Replacement of Lighting Fixture |
| ☐ Repair of Security Alarm | ☐ Additional Wiring / Rewiring | ☐ Replacement of Security Alarm |
| ☐ Repair of Aircon | ☐ Cleaning of Signage Lighting Fixture | ☐ Replacement of Aircon |
| | ☐ Cleaning of Aircon | ☐ Replacement busted Light |

Description / Particulars (additional information of request & reason)

ADDITIONAL GONDOLA FOR BACK TO SCHOOL

GONDOLA FOR STOCKROOM

14 pcs. Post (4ft / 6ft)	5 pcs. Post (6ft.)
20 pcs. FEET	5 pcs. FEET
96 pcs. bracket	48 pcs. bracket
32 pcs. 1M Shelves	14 pcs. 1.2M Shelves
14 pcs. 1.2M Shelves	
16 pcs. Endcap Shelves	

OTHER

☐ Mall Admin concern / request

VISUAL & PD section

Work Assigned To		Date of Work
Action Taken		
Work completed by	Completion Date	Acknowledged by/Date: (Store)

Refer To _____ Date of Work _____

Prepared by/Date <u>Princess Sanlitan 03/21/2026</u>	Noted by/Date (Visual & PD Manager)	Approved by/Date President
---	-------------------------------------	-----------------------------------