

Needs Assessment Report – Aputuogya Market Complex

Purpose: To identify the need for a structured market facility in Aputuogya.

Current Situation: Traders operate in scattered roadside spaces without sanitation or storage.

Identified Needs:

- Organized stalls
- Storage facilities
- Sanitation services
- Safe trading environment

Conclusion: There is a strong infrastructure gap affecting productivity and safety.