

AUTO CLAIMS DIRECT

Workfile ID:

d5e6adb2

3196 WILLOW CREEK RD

PRESCOTT, AZ 86301

Phone: (602) 773-1961

For:

AUTO CLAIMS DIRECT

NATIONWIDE MUTUAL INSURANCE COMPANY

Preliminary Estimate**Owner: ALSTON, JESSICA****Job Number:**Written By: Vernon Long
Adjuster: Boone, Brittany, (833) 369-2567 Business

Insured: ALSTON, JESSICA

Policy #:

Claim #: 664723-GQ-1

Type of Loss: Comprehensive

Date of Loss: 8/8/2025 12:00 PM

Days to Repair: 2

Point of Impact: 29 Vandalism

Owner:

ALSTON, JESSICA

1115 LICKSKILLET RD

Warrenton, NC 27589

(252) 915-6481 Cell

(252) 915-6481 Business

Inspection Location:

Jessica Alston

211 BARHAM LN

Henderson, NC 27537

Other

(252) 915-6481 Day

Repair Facility:**VEHICLE**

2025 CHEV Equinox LT1 FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection WHITE

VIN: 3GNAXHEG0SL290421

License: GRLFGHTR

State: NC

Production Date: 2/2025

Odometer: 6,826

Condition: Excellent

Interior Color:

WHITE

TRANSMISSION

Automatic Transmission

Tilt Wheel

AM Radio

Communications System

POWER

Power Steering

Cruise Control

FM Radio

Hands Free Device

Power Brakes

Rear Defogger

Stereo

Xenon or L.E.D. Headlamps

Power Windows

Keyless Entry

Search/Seek

Blind Spot Detection

Power Locks

Alarm

Auxiliary Audio Connection

Lane Departure Warning

Power Mirrors

Message Center

Satellite Radio

SEATS

Heated Mirrors

Steering Wheel Touch Controls

Drivers Side Air Bag

Cloth Seats

DECOR

Telescopic Wheel

Passenger Air Bag

Bucket Seats

Dual Mirrors

Heated Steering Wheel

Anti-Lock Brakes (4)

Heated Seats

Privacy Glass

Navigation System

4 Wheel Disc Brakes

WHEELS

Console/Storage

Backup Camera

Traction Control

Aluminum/Alloy Wheels

CONVENIENCE

Parking Sensors

Stability Control

PAINT

Air Conditioning

Remote Starter

Front Side Impact Air Bags

Clear Coat Paint

Intelligent Cruise

Head/Curtain Air Bags

Preliminary Estimate

Owner: ALSTON, JESSICA

Job Number:

2025 CHEV Equinox LT1 FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection WHITE

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FENDER						
2	*	Algn LT Fender				<u>1.0</u>	
3		R&I LT Wheelhouse liner				0.4	
4	FRONT DOOR						
5		R&I LT R&I trim panel				0.5	
6		R&I RT R&I trim panel				0.5	
7	Repl	RT Handle, outside	13563173	1	64.22	0.4	0.5
8		Add for Clear Coat					0.1
9		Dis/reassmble to refn				0.2	
10	Repl	LT Handle, outside	13563171	1	78.53	0.4	0.5
11		Overlap Minor Panel					-0.2
12		Add for Clear Coat					0.1
13		Dis/reassmble to refn				0.2	
14	*	Rpr RT Upper cover				<u>0.5</u>	0.6
15		Overlap Minor Panel					-0.2
16		Add for Clear Coat					0.1
17	REAR DOOR						
18	Repl	RT Handle, outside	13563181	1	52.52	0.4	0.4
19		Overlap Minor Panel					-0.2
20		Add for Clear Coat					0.1
21		Dis/reassmble to refn				0.2	
22	R&I	RT R&I trim panel				0.4	
23	LIFT GATE						
24	Repl	Wiper arm	26527412	1	20.10	0.2	
25	R&I	Lower gate trim w/power lift gate				0.3	
26	VEHICLE DIAGNOSTICS						
27	*	Rpr Pre-repair scan				m <u>0.5</u> M	
28	*	Rpr Post-repair scan				m <u>0.5</u> M	
		SUBTOTALS			215.37	6.6	1.8

NOTES

Prior Damage Notes:
NO UPD VISIBLE

Preliminary Estimate

Owner: ALSTON, JESSICA

Job Number:

2025 CHEV Equinox LT1 FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection WHITE

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			215.37
Body Labor	5.6 hrs @	\$ 55.00 /hr	308.00
Paint Labor	1.8 hrs @	\$ 55.00 /hr	99.00
Mechanical Labor	1.0 hrs @	\$ 95.00 /hr	95.00
Paint Supplies	1.8 hrs @	\$ 44.00 /hr	79.20
Subtotal			796.57
Sales Tax	\$ 796.57 @	6.7500 %	53.77
Total Cost of Repairs			850.34
Deductible			100.00
Total Adjustments			100.00
Net Cost of Repairs			750.34

MyPriceLink Estimate ID / Quote ID:

1385729479405477888 / 147206308

Supplements: <http://acdcorp.com/supp>

*THIS IS NOT AN AUTHORIZATION TO REPAIR OR ACCEPTANCE OF LIABILITY

*THIS IS NOT A FINAL APPROVED ESTIMATE, NOR ACCEPTANCE TO PAY

*SHOP TO PROVIDE AUTHORIZATION TO REPAIR/DIRECTION TO PAY FROM OWNER

*ESTIMATE PREPARED BY: E. Kolkhorst

*NO SUPPLEMENTS WITHOUT PRIOR AUTHORIZATION: ALL SUPPLEMENTS,
CALL FOR SUPPLEMENT REQUEST LISTED NUMBER PAGE 1 ORIGINAL ESTIMATE

*REQUIREMENT FOR ALL SUPPLEMENT REQUESTS: INVOICES, OLD PARTS, PHOTOS
HIDDEN /ADDITIONAL DAMAGE; MUST BE DOCUMENTED BY JPG PHOTOGRAPH

*TEAR DOWN PRIOR TO REPAIRS COMMENCING OR PARTS ORDERED

W/WRITTEN OWNER AUTHORIZATION

*AGREED PRICE (N) ESTIMATE TO SHOP (N)

*ESTIMATE MAILED TO THE OWNER (N)

*TOTAL LOSS (N) CCC REQUEST #

*RECYCLED PARTS USED (N)

*AFTERMARKET PARTS USED (Y)

THIS IS NOT AN AUTHORIZATION TO REPAIR. THIS IS AN APPRAISAL OF
DAMAGES ONLY. NO APPRAISER HAS THE AUTHORITY TO AUTHORIZE REPAIRS.
AUTHORIZATION AND GUARANTEE OF PAYMENT CAN ONLY BE GIVEN BY THE OWNER
OF THE VEHICLE. ACD (AUTOCCLAIMS DIRECT) AND ITS CLIENTS ASSUME NO
RESPONSIBILITY FOR REPAIR QUALITY AND SAFETY. ACD (AUTOCCLAIMS DIRECT)
SPECIFIES AND INTENDS THAT ALL REPAIRS AND PART REPLACEMENTS LISTED
HEREON ARE MADE IN STRICT ACCORDANCE WITH THE MANUFACTURER'S
RECOMMENDATIONS AND SPECIFICATIONS. SUPPLEMENTAL DAMAGE IS SUBJECT TO
REINSPECTION. FOR YOUR PROTECTION.

Preliminary Estimate

Owner: ALSTON, JESSICA

Job Number:

2025 CHEV Equinox LT1 FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection WHITE

NOTE: YOU HAVE THE RIGHT TO SELECT THE BODY SHOP THAT WILL REPAIR YOUR VEHICLE.

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR1GV17, CCC Data Date 08/08/2025, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category.
X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category.
M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel.

CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber.

D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part.

O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Owner: ALSTON, JESSICA

Job Number:

2025 CHEV Equinox LT1 FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection WHITE

ALTERNATE PARTS USAGE

2025 CHEV Equinox LT1 FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection WHITE

VIN:	3GNAXHEG0SL290421	Production Date:	2/2025	Interior Color:
License:	GRLFGHTR	Odometer:	6,826	Exterior Color: WHITE
State:	NC	Condition:	Excellent	

Alternate Part Type	Selection Method	# Of Times Notified Of Available Parts	# Of Parts Selected
Aftermarket	Automatically List	0	0
Optional OEM	Automatically List	0	0
Reconditioned	Automatically List	0	0
Recycled	N/A	0	0

Preliminary Estimate

Owner: ALSTON, JESSICA

Job Number:

2025 CHEV Equinox LT1 FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection WHITE

RECALL INFO

2025 CHEV Equinox LT1 FWD 4D UTV 4-1.5L Turbocharged Gasoline Direct Injection WHITE

VIN: 3GNAXHEG0SL290421

Production Date: 2/2025

Interior Color:

License: GRLFGHTR

Odometer: 6,826

Exterior Color: WHITE

State: NC

Condition: Excellent