

Supplement of Record 1 with Summary

Owner: Shingleton, Julia

Job Number:

Written By: VERNON LONG
Adjuster: Sporman, Tiffany

Insured: Spartan Fire & Emergency Apparatus, Inc
Policy #: Claim #: 10382231
Type of Loss: Collision Date of Loss: 1/22/2026 12:00 AM Days to Repair: 7
Point of Impact: 03 Right T-Bone (Right Side)

Owner:	Inspection Location:	Repair Facility:
Shingleton, Julia	Shingleton, Julia	
1022 Evolve Dr	1022 Evolve Dr	
GARNER, NC 27529	GARNER, NC 27529	
(252) 904-3622 Business	Home	
	(252) 904-3622 Business	

VEHICLE

2015 HOND Civic Sedan EX w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI SILVER

VIN: 19XFB2F86FE038538	Production Date: 1/2015	Interior Color:
License: LLZ1688	Odometer: UNK	Exterior Color: SILVER
State: NC	Condition: Good	

TRANSMISSION

Automatic Transmission

POWER

Power Steering

Power Brakes

Power Windows

Power Locks

Power Mirrors

DECOR

Dual Mirrors

Tinted Glass

Console/Storage

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Alarm

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

Climate Control

Backup Camera

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

CD Player

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

ROOF

Electric Glass Sunroof

SEATS

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control

Stability Control

Supplement of Record 1 with Summary

Owner: Shingleton, Julia

Job Number:

2015 HOND Civic Sedan EX w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI SILVER

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER					
2	R&I	R&I bumper cover				1.4	
3		FRONT LAMPS					
4	R&I	RT R&I headlamp assy				0.3	
5		FENDER					
6	*	Blnd RT Fender sedan					<u>0.9</u>
7	R&I	RT Fender liner sedan, all				0.3	
8	S01	Repl Mud guard sedan, front set w/o Si	08P08TR0100R1	1	30.00	0.4	
9		FRONT DOOR					
10	*	Repl LKQ RT door assy; sedan +25%	67010TR6C80ZZ	1	<u>636.25</u>	1.5	3.0
11		Add for Clear Coat					1.2
12	R&I	RT Door w/strip US built				0.5	
13	R&I	RT Belt molding				0.3	
14	R&I	RT Corner molding US built					
15	R&I	RT Pillar molding US built				0.2	
16	*	R&I RT Black out tape US built				<u>0.3</u>	
17	R&I	RT R&I mirror				0.4	
18	R&I	RT Moveable glass Honda LX, EX, EX-L, Si				0.4	
19	R&I	RT Run channel				0.3	
20	R&I	RT Upper guide				0.2	
21	R&I	RT Window regulator				0.3	
22	R&I	RT Handle, outside painted w/o smart entry alabaster slv				0.4	
23	R&I	RT R&I trim panel				0.4	
24	#	DETRIM LKQ DOOR		1		1.5	
25		REAR DOOR					
26	R&I	RT Door w/strip US built				0.5	
27	*	Repl LKQ RT door assy; Sedan +25%	67510TR6C80ZZ	1	<u>275.00</u>	1.5	2.9
28		Overlap Major Adj. Panel					-0.4
29		Add for Clear Coat					0.5
30	R&I	RT Water shield Type 2				0.1	
31	R&I	RT Belt molding				0.3	
32	R&I	RT Pillar molding front US built				0.2	
33	*	R&I RT Black out tape US built				<u>0.3</u>	
34	R&I	RT Pillar molding rear US built				0.2	
35	R&I	RT Moveable glass Honda w/o HF				0.4	
36	R&I	RT Window regulator				0.3	
37	*	R&I RT Run channel				<u>0.3</u>	
38	R&I	RT Fixed glass Honda, w/o HF				0.4	
39	R&I	RT Handle, outside painted alabaster slv				0.4	
40	R&I	RT R&I trim panel				0.4	

Supplement of Record 1 with Summary

Owner: Shingleton, Julia

Job Number:

2015 HOND Civic Sedan EX w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI SILVER

41	QUARTER PANEL						
42	*		Blnd	RT Quarter panel			<u>1.1</u>
43	*		R&I	RT Mud guard			<u>0.2</u>
44	REAR LAMPS						
45			R&I	RT Tail lamp assy			0.2
46	REAR BUMPER						
47			R&I	R&I bumper cover			1.0
48	VEHICLE DIAGNOSTICS						
49	*	S01	Rpr	Pre-repair scan	m		<u>0.5</u> M
50	*	S01	Rpr	Post-repair scan	m		<u>0.5</u> M
51	MISCELLANEOUS OPERATIONS						
52	**	S01	Subl	A/M Hazardous waste removal	1	3.50 X	
53	**	S01	Repl	A/M Cover/Bag vehicle	1	5.00 T	0.2
54	**	S01	Repl	A/M Seam sealer	1	25.00 T	0.3
SUBTOTALS					974.75	17.3	9.2

NOTES

Prior Damage Notes:
NO UPD VISIBLE

ESTIMATE TOTALS

Category	Basis			Rate	Cost \$
Parts					941.25
Body Labor	16.3 hrs	@		\$ 55.00 /hr	896.50
Paint Labor	9.2 hrs	@		\$ 55.00 /hr	506.00
Mechanical Labor	1.0 hrs	@		\$ 95.00 /hr	95.00
Paint Supplies	9.2 hrs	@		\$ 40.00 /hr	368.00
Miscellaneous					33.50
Subtotal					2,840.25
Sales Tax	\$ 2,836.75	@		7.0000 %	198.57
Total Cost of Repairs					3,038.82
Total Adjustments					0.00
Net Cost of Repairs					3,038.82

Supplement of Record 1 with Summary

Owner: Shingleton, Julia

Job Number:

2015 HOND Civic Sedan EX w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI SILVER

SUPPLEMENT SUMMARY

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
Deleted Items							
8	*	R&I RT Mud guard sedan, front set w/o Si				-0.2	
Added Items							
8	S01	Repl Mud guard sedan, front set w/o Si	08P08TR0100R1	1	30.00	0.4	
48	VEHICLE DIAGNOSTICS						
49	*	S01 Rpr Pre-repair scan			m	0.5	M
50	*	S01 Rpr Post-repair scan			m	0.5	M
51	MISCELLANEOUS OPERATIONS						
52	**	S01 Subl A/M Hazardous waste removal		1	3.50	X	
53	**	S01 Repl A/M Cover/Bag vehicle		1	5.00	T	0.2
54	**	S01 Repl A/M Seam sealer		1	25.00	T	0.3
SUBTOTALS					63.50	1.7	0.0

CHANGES TO ADJUSTMENTS

TOTALS SUMMARY

Category	Basis	Rate	Cost \$
Parts			30.00
Body Labor	0.7 hrs @	\$ 55.00 /hr	38.50
Mechanical Labor	1.0 hrs @	\$ 95.00 /hr	95.00
Miscellaneous			33.50
Subtotal			197.00
Sales Tax	\$ 193.50 @	7.0000 %	13.55
Additional Supplement Taxes			-0.01
Total Supplement Amount			210.54
NET COST OF SUPPLEMENT			210.54

Supplement of Record 1 with Summary

Owner: Shingleton, Julia

Job Number:

2015 HOND Civic Sedan EX w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI SILVER

CUMULATIVE EFFECTS OF SUPPLEMENT(S)

Estimate	2,828.28	VERNON LONG
Supplement S01	210.54	VERNON LONG
Workfile Total:	\$ 3,038.82	
NET COST OF REPAIRS:	\$ 3,038.82	

This estimate has been prepared by an independent appraiser based only on damage that could be seen at the time of the inspection. Hidden damage may be found upon tear down. This estimate has been prepared based on Frankenmuth Mutual Company's guidelines regarding parts usage and specifications. This estimate may have been prepared based on aftermarket crash parts supplied by a vendor other than the manufacturer of your vehicle. Warranties that apply to these parts are provided by the manufacturer or vendor of these parts. CAPA certified alternate parts are in use where prescribed. All repairs and/or part replacement listed herein must be performed in strict adherence to the vehicle's specifications and recommendations. In the event of a supplement, all appropriate paperwork must be completed prior to the vehicle being delivered. The independent appraiser should be contacted immediately after tear down for review and approval of additional damage repairs.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AUTOMOBILE PARTS NOT MADE BY THE ORIGINAL MANUFACTURER. PARTS USED IN THE REPAIR OF YOUR VEHICLE MADE BY OTHER THAN THE ORIGINAL MANUFACTURER ARE REQUIRED TO BE AT LEAST EQUIVALENT IN TERMS OF FIT, QUALITY, PERFORMANCE, AND WARRANTY TO THE ORIGINAL MANUFACTURER PARTS THEY ARE REPLACING.

Owner: Shingleton, Julia

Job Number:

2015 HOND Civic Sedan EX w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI SILVER

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ARG4449, CCC Data Date 02/16/2026, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Bld=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Supplement of Record 1 with Summary

Owner: Shingleton, Julia

Job Number:

2015 HOND Civic Sedan EX w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI SILVER

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
10	LKQ - EAST CAROLINA JIMMIE FOSS 7135 HWY. 70 WEST LAGRANGE NC 28551 (800) 682-9633	#B35648 LKQ RT door assy; sedan +25% Door, Rt Ft RH,R, (ELECTRIC), SDN, 1.8L, LX (INCLUDES US S#B35648	\$ 509.00
27	WAYNE AUTO SALVAGE JUSTIN MYERS 1911 US HIGHWAY 117 S. GOLDSBORO NC 27530 (919) 734-3958	#N10745 LKQ RT door assy; Sedan +25% Door, Rt Rr RT SIDE DOOR-000,PAINT CODE-NH797M,GRY,4DR,EX,S#N107458	\$ 220.00