Final Handover Checklist - Stationary BESS (India) - BESS-100 RS

Generated at: 2026-02-27T12:38:17.311871+00:00

Model: UNITYESS-125-261-OS | Location: Delhi, India

Digital Handover QR

Scan for BESS handover data

QR payload mode: FULL

Project Information

[x] Project: BESS Site Handover

[x] Site / Plant ID: 1

[x] Owner / Customer: System Admin

[x] OEM / EPC: UnityESS / Ornate Solar

[x] Commissioning Date: 2026-02-26T07:19:59.854951+00:00

[x] Handover Date: 2026-02-26T07:19:59.854951+00:00

[x] Lead Commissioning Engineer: System Admin

BESS Unit Details

[x] Serial Number: BESS-100 RS

[x] Model Number: UNITYESS-125-261-OS

[x] Model Capacity (kWh): 261.0

[x] Current Stage: PORT_ARRIVED

[x] Manufactured Date: -

[x] Country: India

[x] City: Delhi

[x] Warehouse: -

[x] Site Address: -

[x] Site Latitude: -

[x] Site Longitude: -

[x] Customer User ID: -

1) Regulatory and Standards Compliance

[x] System compliance checked against CEA connectivity requirements and approvals.

[x] Applicable BIS / IS battery compliance and test certificates are documented.

[x] Applicable MNRE / national ESS policy and project submission documents are attached.

2) Documentation Handed Over

[x] As-built SLD and GA drawings handed over.

[x] FAT, SAT, and performance reports attached.

[x] O&M manual, emergency SOP, and warranty pack handed over.

[x] Protection settings, earthing reports, and commissioning test records verified.

3) Safety and Site Readiness

[x] Fire detection and suppression commissioning report completed.

[x] E-STOP and isolation process demonstrated at site.

[x] Site signage, access control, ventilation, and segregation verified.

4) Controls, Communication and Training

[x] EMS/SCADA telemetry and control command validation completed.

[x] Remote monitoring credentials and access rights handed over.

[x] Operator handover session completed with attendance records.

Signatures (Accepted)

Site Engineer: System Admin

Signed At: 2026-02-26T10:40:19.415245+00:00

Customer: System Admin

Signed At: 2026-02-26T07:19:59.854951+00:00

5) Functional and Stage Completion Summary

[x] SITE_ARRIVED: 3/3 checklist items completed

[x] CIVIL_INSTALLATION: 7/7 checklist items completed

[x] DC_INSTALLATION: 7/7 checklist items completed

Final Handover Checklist - Stationary BESS (India) - BESS-100 RS

Generated at: 2026-02-27T12:38:17.311871+00:00

Checklist completion with photo evidence

Checklist Completion with Photos

Stage: SITE_ARRIVED

1. [DONE] Inspect unit for physical damage

   Mandatory: YES | Photo Required: YES

   Notes: Yes

   Photo:

/media/checklist_photos/checklist_1_1772025057497_d1a0d4222d644f2a91957af7c56f0d79.jpg

2. [DONE] Verify serial number matches delivery note

   Mandatory: YES | Photo Required: NO

   Notes: Yes

   Photo:

/media/checklist_photos/checklist_2_1772025102719_c7d17bfdd63f45ae8a779a5dd7080f8d.jpg

3. [DONE] Confirm correct unit delivered to correct site

   Mandatory: YES | Photo Required: NO

   Notes: Yes

   Photo:

/media/checklist_photos/checklist_3_1772025112086_9a11953cf7864b6496c8b4aa85235894.jpg

Stage: CIVIL_INSTALLATION

1. [DONE] Foundation >=800x800mm concrete pad confirmed

   Mandatory: YES | Photo Required: NO

   Notes: Yes

   Photo:

/media/checklist_photos/checklist_4_1772025152569_a97898244de0423fb6fc2c20d371a715.jpg

Final Handover Checklist - Stationary BESS (India) - BESS-100 RS

Generated at: 2026-02-27T12:38:17.311871+00:00

Checklist stage: CIVIL_INSTALLATION

2. [DONE] Ground level within +/-5mm tolerance (spirit level)

Mandatory: YES | Photo Required: NO

Notes: Yes

Photo:

/media/checklist_photos/checklist_5_1772025162483_e62f97b27a0e4bff8e448ad5919785e4.jpg

3. [DONE] BESS cabinet placed per layout drawing

Mandatory: YES | Photo Required: NO

Notes: Yes

Photo:

/media/checklist_photos/checklist_6_1772025174020_366f2bfc047a4508b7fc80111b96cc0b.jpg

4. [DONE] Cabinet secured with M24 anchor bolts to specified torque

Mandatory: YES | Photo Required: NO

Notes: Yes

Photo:

/media/checklist_photos/checklist_7_1772025187012_55ea118018b44dfcb393a80af46fa26b.jpg

5. [DONE] Minimum 1000mm clearance on all 4 sides confirmed

Mandatory: YES | Photo Required: NO

Notes: Yes

Photo:

/media/checklist_photos/checklist_8_1772025197935_bcbf75e285cb4cb281fd8dce9eec0ccc.jpg

6. [DONE] Anti-vibration pads installed under cabinet

Mandatory: YES | Photo Required: NO

Notes: Yes

Photo:

/media/checklist_photos/checklist_9_1772025216919_8f490beda7bc4fbc880653723ba9a221.jpg

Final Handover Checklist - Stationary BESS (India) - BESS-100 RS

Generated at: 2026-02-27T12:38:17.311871+00:00

Checklist stage: CIVIL_INSTALLATION

7. [DONE] Post-placement photo captured

Mandatory: YES | Photo Required: YES

Notes: Yes

Photo:

/media/checklist_photos/checklist_10_1772025229587_921e32a65d4247d68d312d2166682845.jpg

Stage: DC_INSTALLATION

1. [DONE] All DC breakers confirmed OFF before wiring

Mandatory: YES | Photo Required: NO

Notes: Yes

Photo:

/media/checklist_photos/checklist_11_1772025275649_265c7dcda5854b368de3ab3b6532205a.jpg

2. [DONE] Battery cluster cables connected per wiring diagram

Mandatory: YES | Photo Required: NO

Notes: Yes

Photo:

/media/checklist_photos/checklist_12_1772025307058_2d7c424f90b64b0ea3c77654eec36871.jpg

3. [DONE] Busbar bolts torqued to spec - blue pen mark by installer

Mandatory: YES | Photo Required: NO

Notes: 1

Photo: -

4. [DONE] Inspector re-torque verified - red pen mark applied

Mandatory: YES | Photo Required: NO

Notes: Yes

Photo: -

5. [DONE] No loose DC connections found

Mandatory: YES | Photo Required: NO

Notes: 1

Photo: -

6. [DONE] Anti-static gloves worn throughout

Mandatory: YES | Photo Required: NO

Notes: 1

Photo: -

Final Handover Checklist - Stationary BESS (India) - BESS-100 RS

Generated at: 2026-02-27T12:38:17.311871+00:00

Checklist stage: DC_INSTALLATION

7. [DONE] BMU boards not touched bare-handed

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

Stage: AC_INSTALLATION

1. [DONE] MCCB1 (AC circuit breaker) confirmed OFF

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

2. [DONE] AC grid cables connected to combiner cabinet

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

3. [DONE] Phase sequence verified A-B-C: 400V between phases

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

4. [DONE] Phase-to-neutral verified: 230V

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

5. [DONE] PE grounding wire connected and secure

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

6. [DONE] All cable entries sealed with sealing compound

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

7. [DONE] No cables routed through air inlet or outlet

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

8. [DONE] Cables of different types separated >=30mm

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

Stage: PRE_COMMISSION

1. [DONE] All wiring connections verified correct

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

2. [DONE] BMS<->EMS communication cables connected

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

3. [DONE] No loose connections throughout the entire unit

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

4. [DONE] AC surge protector indicator is GREEN

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

Final Handover Checklist - Stationary BESS (India) - BESS-100 RS

Generated at: 2026-02-27T12:38:17.311871+00:00

Checklist stage: PRE_COMMISSION

5. [DONE] UPS functional and output confirmed

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

6. [DONE] CO2 fire extinguisher present on site

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

7. [DONE] "Do Not Close" warning signs on all switches

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

Stage: COLD_COMMISSION

1. [DONE] MCCB2 (auxiliary power) turned ON

   Mandatory: YES | Photo Required: NO

   Notes: Yes

   Photo: -

2. [DONE] AC output button pressed - indicator GREEN

   Mandatory: YES | Photo Required: NO

   Notes: Yes

   Photo: -

3. [DONE] UPS started successfully

   Mandatory: YES | Photo Required: NO

   Notes: Yes

   Photo: -

4. [DONE] BMS contactor status: CLOSED after 30 seconds

   Mandatory: YES | Photo Required: NO

   Notes: Yes

   Photo: -

5. [DONE] PCS indicator illuminated

   Mandatory: YES | Photo Required: NO

   Notes: Yes

   Photo: -

6. [DONE] EMS web interface accessible

   Mandatory: YES | Photo Required: NO

   Notes: Te

   Photo: -

7. [DONE] Zero alarms present at startup

   Mandatory: YES | Photo Required: NO

   Notes: Yws

   Photo: -

Stage: HOT_COMMISSION

1. [DONE] Charging test: SOC increasing confirmed

   Mandatory: YES | Photo Required: YES

   Notes: 1

   Photo:

/media/checklist_photos/checklist_40_1772090338521_a8eb6ca6861e47e08282b5aad1e41aad.jpg

Final Handover Checklist - Stationary BESS (India) - BESS-100 RS

Generated at: 2026-02-27T12:38:17.311871+00:00

Checklist stage: HOT_COMMISSION

2. [DONE] Discharging test: load response verified

   Mandatory: YES | Photo Required: NO

   Notes: Q

   Photo: -

3. [DONE] Grid synchronization: voltage and frequency within tolerance

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

4. [DONE] No alarms in EMS dashboard

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

5. [DONE] Performance test completed and result logged

   Mandatory: YES | Photo Required: NO

   Notes: 1

   Photo: -

Stage: FINAL_ACCEPTANCE

1. [DONE] QA team sign-off obtained

   Mandatory: YES | Photo Required: NO

   Notes: Done from Postman

   Photo: https://example.com/photo.jpg

2. [DONE] Customer acceptance signature collected

   Mandatory: YES | Photo Required: YES

   Notes: 1

   Photo:

/media/checklist_photos/checklist_46_1772090397371_fe42a24aa8af4fc282aac8a668b6d92b.jpg

3. [DONE] Warranty start date recorded in system

   Mandatory: YES | Photo Required: NO

   Notes: Yw

   Photo: -

4. [DONE] All checklist documentation uploaded

   Mandatory: YES | Photo Required: NO

   Notes: Yes

   Photo: -

5. [DONE] Full photo set of installation captured

   Mandatory: YES | Photo Required: YES

   Notes: Uee

   Photo:

/media/checklist_photos/checklist_49_1772090420093_ccc2c25c83374baf9594f635326f46e5.jpg