

plantId * required The GUID of the plant the sensor is attached to.
string(\$uuid)
(path)

1DD75EDA-DDE5-4594-ABE5-153E2342C1

Request body

application/json

The telemetry data (e.g., soil moisture, light levels).

Edit Value | Schema

```
{
  "Timestamp": "2026-02-01T02:37:25.204Z",
  "Temperature": 30,
  "Humidity": null,
  "AirSensorStatus": "OK",
  "SoilMoisture": 300,
  "PH": 7,
  "Potassium": 80,
  "Phosphorus": 60,
  "Nitrogen": null,
  "SoilSensorStatus": "Faulty"
}
```

Execute

Clear

Responses

Curl

```
curl -X 'POST' \
  'https://roxana-noncongruous-unschoolingly.ngrok-free.dev/api/SensorData/Add/1DD75EDA-DDE5-4594-ABE5-153E2342C1C9' \
  -H 'accept: */*' \
  -H 'Authorization: Bearer eyJhbGciOiJIUzI1NiIsInR5cCI6IkpXVCJ9.eyJodHRwOi8vc2NoZW1hcy40bXZlbnQ9Yy93cy8yMDAxLzA1L2lkZm5hbnR5L2N5Ym1icy9uYm1laW1nbnR5L2m1l1c1I6IjY1NGQyMzQ1L2NmZGI1NGZlM585MwZlWVJNTQ4YmZjODM' \
  -H 'Content-Type: application/json' \
  -d '{
    "Timestamp": "2026-02-01T02:37:25.204Z",
    "Temperature": 30,
    "Humidity": null,
    "AirSensorStatus": "OK",
    "SoilMoisture": 300,
    "PH": 7,
    "Potassium": 80,
    "Phosphorus": 60,
    "Nitrogen": null,
    "SoilSensorStatus": "Faulty"
  }'
```

Request URL

https://roxana-noncongruous-unschoolingly.ngrok-free.dev/api/SensorData/Add/1DD75EDA-DDE5-4594-ABE5-153E2342C1C9

Server response

Code Details

200

Response body

Sensor data added successfully.



Download

Response headers

```
content-type: text/plain; charset=utf-8
date: Sun, 01 Feb 2026 06:40:57 GMT
ngrok-agent-ips: 176.29.59.24
server: Kestrel
```

Responses

Code Description

Links



Hardware Alert 9:40 AM



Greenhouse : Soil Sensor Array (Mod-
bus/NPK) Failure Detected for Plant: ...