


AI Medical Device Monitoring Dashboard




Device Status: ✔ All Systems Normal

Efficiency: 91%


 Next Maintenance: In 7 Days





Recent Maintenance History

-  MRI Scanner - Calibration check (Feb 10, 2025)
-  Ventilator - Filter replacement (Jan 25, 2025)
-  Infusion Pump - Battery check (Jan 15, 2025)

AI Insights & Alerts

 ****Warning:**** The ventilator in ICU-3 is showing ****slight pressure instability.**** A technician should review it.

 ****Efficiency Notice:**** The MRI scanner's ****power consumption increased by 10% this month.**** Consider checking cooling efficiency.

 ****Recommendation:**** Regular filter replacements have improved the ****infusion pump's performance by 8%.**** Keep up the maintenance routine!