


# PCB Defect Inspection Report

## Inspection Summary

|                      |            |                   |
|----------------------|------------|-------------------|
| Health Score: 55/100 | Defects: 3 | Est. Cost: \$2.25 |
|----------------------|------------|-------------------|



## Technician Work Order

| Defect | Action               | Time  | Cost (\$) |
|--------|----------------------|-------|-----------|
| Spur   | Scrape excess copper | 1 min | \$0.75    |
| Spur   | Scrape excess copper | 1 min | \$0.75    |
| Spur   | Scrape excess copper | 1 min | \$0.75    |