

## ☒ 오류의 영향을 받는 부품 (4)

커버



207.73 x 20.02 x 13.21 mm  
4980 mm<sup>3</sup>

오류 유형

- 메쉬가 닫혀 있지 않습니다.

커버-1



207.73 x 20.02 x 13.21 mm  
4980 mm<sup>3</sup>

오류 유형

- 메쉬가 닫혀 있지 않습니다.

커버-2



207.73 x 20.02 x 13.21 mm  
4980 mm<sup>3</sup>

오류 유형

- 메쉬가 닫혀 있지 않습니다.

커버-3



207.73 x 20.02 x 13.21 mm  
4980 mm<sup>3</sup>

오류 유형

- 메쉬가 닫혀 있지 않습니다.

 부품 (16)

<p><b>버튼</b></p>  <p>17.17 x 10.64 x 6.03 mm 379 mm<sup>3</sup></p> <hr/> <hr/> <hr/>	<p><b>버튼-1</b></p>  <p>17.17 x 10.64 x 6.03 mm 379 mm<sup>3</sup></p> <hr/> <hr/> <hr/>
<p><b>버튼-2</b></p>  <p>17.17 x 10.64 x 6.03 mm 379 mm<sup>3</sup></p> <hr/> <hr/> <hr/>	<p><b>버튼-3</b></p>  <p>17.17 x 10.64 x 6.03 mm 379 mm<sup>3</sup></p> <hr/> <hr/> <hr/>
<p><b>본체</b></p>  <p>208.54 x 20.11 x 10.5 mm 4717 mm<sup>3</sup></p> <hr/> <hr/> <hr/>	<p><b>본체-1</b></p>  <p>208.54 x 20.11 x 10.5 mm 4717 mm<sup>3</sup></p> <hr/> <hr/> <hr/>
<p><b>본체-2</b></p>  <p>208.54 x 20.11 x 10.5 mm 4717 mm<sup>3</sup></p> <hr/> <hr/> <hr/>	<p><b>본체-3</b></p>  <p>208.54 x 20.11 x 10.5 mm 4717 mm<sup>3</sup></p> <hr/> <hr/> <hr/>
<p><b>스위치부</b></p>  <p>71.6 x 15.2 x 5.68 mm 1037 mm<sup>3</sup></p> <hr/> <hr/> <hr/>	<p><b>스위치부-1</b></p>  <p>71.6 x 15.2 x 5.68 mm 1037 mm<sup>3</sup></p> <hr/> <hr/> <hr/>
<p><b>스위치부-2</b></p>  <p>71.6 x 15.2 x 5.68 mm 1037 mm<sup>3</sup></p> <hr/> <hr/> <hr/>	<p><b>스위치부-3</b></p>  <p>71.6 x 15.2 x 5.68 mm 1037 mm<sup>3</sup></p> <hr/> <hr/> <hr/>

칫솔헤드 Sus전극 용



27.8 x 10.79 x 4 mm  
696 mm<sup>3</sup>

칫솔헤드 Sus전극 용-1



27.8 x 10.79 x 4 mm  
696 mm<sup>3</sup>

칫솔헤드 Sus전극 용-2



27.8 x 10.79 x 4 mm  
696 mm<sup>3</sup>

칫솔헤드 Sus전극 용-3



27.8 x 10.79 x 4 mm  
696 mm<sup>3</sup>