

Check-In Report

| | |
|---------------|----------|
| User | admin |
| Agent | shah |
| Property Name | tricity |
| Object Name | flat 101 |

Object Details

| Object Detail | Property Name |
|----------------|---------------|
| Soap dispenser | tricity |
| heater | tricity |
| plug | tricity |
| kitchen | tricity |
| dining room | tricity |

Furniture Inspections

| Cleaning Type | Photos | Description |
|------------------|--------------------------------------|------------------------------|
| General Cleaning | /media/inspection_photos/Screenshots | from_2023-06-20_12-44-56.png |