

Final Report Page

M/C Room

1 - M/C Room & Motor Area Check & Clean : Already resolved

,

2 - Motor Main Rope Check & Clean : Already resolved

,

3 - Rope Thimbal & U Clamp Ckeck & Tight : Yes

,

4 - Motor & Pully Level Check : Already resolved

,

5 - Osg Working Check & Clean : No

,

6 - Controller Cover, Lock & Clean : Yes

,

7 - Manual Rescue Lever Working Check : Already resolved

,

8 - Three Supply & Earthing Proper Available : Already resolved

,

Cabin, Floors

1 - Working smooth when the lift ride up & down : Already resolved

,

2 - All lop and cop with display working : Already resolved

,

3 - Cabin light & fan working : Already resolved

,

4 - Ard and alram working : Already resolved

,

5 - Car door open,close smooth : Yes

,

6 - Floor level equal all floors : No

,

7 - All doors must mechanically lock : No

,

8 - All doos must electrically work with circuit (door bypass) : No

,

9 - All doors must open with lift key : Already resolved

,

Cartop ,Shaft

1 - Shaft light working : Already resolved

,

2 - Cartop up,down,stop all switch working : Already resolved

,

3 - Cartop light workin with switch : Already resolved

,

4 - Final limit switch all working : Already resolved

,

5 - Reed switch and magnet proper fix & aline : Already resolved

,

6 - Cartop pully rope gard proper setup : Already resolved

,

7 - Cartop OSG coupling with car cabin proper setup : Already resolved

,

8 - Car door safety switch must work in circuit (door bypass) : Already resolved

,

9 - Car cabin main shoe liner check : Already resolved

,

10 - Safety lock functionally check, mec,& ele. : Already resolved

,

11 - Cwt, main shoe liner check : Already resolved

,

12 - All nut and bolts checked and they are tighten : Already resolved

,

Pit Area

1 - Lift pit must clean and tidy : Already resolved

,

2 - Pit light wokning : Already resolved

,

3 - Car & cwt buffer proper fix : Already resolved

,

4 - OSG lower part proper fix and working : Already resolved

,

5 - Pit clean : No

,

6 - Oil cup refill car & cwt : Already resolved

,

7 - Get customer signature on service report : Already resolved

Payment Data

`{"Total_Amount":"Rs. 5000","Payment_Method":"Cash"}`

Signature Name

raaaju

Number

245899

Client Signature

