### **Final Report Page**

#### **Cabin, Floors**

```
1 - Working smooth when the lift ride up & down: Already resolved
2 - All lop and cop with display working: Already resolved
3 - Cabin light & fan working: Already resolved
4 - Ard and alram working: Already resolved
5 - Car door open, close smooth: Already resolved
6 - Floor level equal all floors: Already resolved
7 - All doors must mechanically lock: Already resolved
8 - All doos must electrically work with circuit (door bypass): Already resolved
9 - All doors must open with lift key: Already resolved
```

#### **Payment Data**

{"Total\_Amount":"Rs. 5000","Payment\_Method":"Cash"}

#### Signature Name

## Number

5285252

# **Client Signature**

