

# AI VEHICLE DAMAGE INSPECTION REPORT

Insurance-Oriented Multi-View Vehicle Damage Assessment

Generated On: 29-06-2026 11:55:03

## VEHICLE VIEWS ANALYSED

- ✓ FRONT
- ✓ BACK
- ✓ LEFT
- ✓ RIGHT

## AI MODELS USED

- Damage Model (YOLOv8)
- Parts Model (YOLOv8)

## OVERALL DAMAGE SUMMARY

| Vehicle Side | Damage Status | Damage Count |
|--------------|---------------|--------------|
| FRONT        | Damaged       | 4            |
| BACK         | Damaged       | 2            |
| LEFT         | Damaged       | 5            |
| RIGHT        | Damaged       | 2            |

## FRONT VIEW ANALYSIS




Figure: FRONT View Damage Inspection

| Component    | Status    | Severity |
|--------------|-----------|----------|
| Fender       | Damaged   | Moderate |
| Front-bumper | No Damage | -        |
| Front-wheel  | No Damage | -        |
| Grille       | No Damage | -        |
| Headlight    | Damaged   | Severe   |
| Hood         | Damaged   | Minor    |

| Damage           | Severity | Raw Cost   | Covered    | Customer Pays |
|------------------|----------|------------|------------|---------------|
| Fender Dent      | Moderate | Rs. 7,500  | Rs. 5,500  | Rs. 2,000     |
| Headlight Damage | Severe   | Rs. 24,000 | Rs. 18,500 | Rs. 5,500     |
| Bonnet Dent      | Severe   | Rs. 18,000 | Rs. 14,000 | Rs. 4,000     |
| Bonnet Dent      | Minor    | Rs. 3,500  | Rs. 2,500  | Rs. 1,000     |

## BACK VIEW ANALYSIS



Figure: BACK View Damage Inspection

| Component     | Status    | Severity |
|---------------|-----------|----------|
| Back-door     | Damaged   | Severe   |
| Back-wheel    | No Damage | -        |
| Back-window   | No Damage | -        |
| Fender        | No Damage | -        |
| Front-door    | Damaged   | Minor    |
| Front-wheel   | No Damage | -        |
| Front-window  | No Damage | -        |
| Hood          | No Damage | -        |
| Mirror        | No Damage | -        |
| Quarter-panel | No Damage | -        |
| Rocker-panel  | No Damage | -        |

| Damage          | Severity | Raw Cost   | Covered    | Customer Pays |
|-----------------|----------|------------|------------|---------------|
| Door Outer Dent | Severe   | Rs. 19,000 | Rs. 12,000 | Rs. 7,000     |
| Door Outer Dent | Minor    | Rs. 4,000  | Rs. 2,000  | Rs. 2,000     |

## LEFT VIEW ANALYSIS




Figure: LEFT View Damage Inspection

| Component    | Status    | Severity |
|--------------|-----------|----------|
| Fender       | Damaged   | Minor    |
| Front-bumper | No Damage | -        |
| Front-door   | No Damage | -        |
| Front-wheel  | No Damage | -        |
| Front-window | No Damage | -        |
| Grille       | No Damage | -        |
| Headlight    | Damaged   | Severe   |
| Hood         | Damaged   | Severe   |
| Mirror       | Damaged   | Severe   |
| Rocker-panel | No Damage | -        |
| Roof         | No Damage | -        |
| Windshield   | No Damage | -        |

| Damage             | Severity | Raw Cost   | Covered    | Customer Pays |
|--------------------|----------|------------|------------|---------------|
| Side Mirror Damage | Severe   | Rs. 11,000 | Rs. 12,500 | Rs. 0         |
| Bonnet Dent        | Severe   | Rs. 18,000 | Rs. 14,000 | Rs. 4,000     |
| Bonnet Dent        | Severe   | Rs. 18,000 | Rs. 14,000 | Rs. 4,000     |

|                  |        |            |            |           |
|------------------|--------|------------|------------|-----------|
| Fender Dent      | Minor  | Rs. 3,500  | Rs. 2,000  | Rs. 1,500 |
| Headlight Damage | Severe | Rs. 24,000 | Rs. 18,500 | Rs. 5,500 |

## RIGHT VIEW ANALYSIS




Figure: RIGHT View Damage Inspection

| Component     | Status    | Severity |
|---------------|-----------|----------|
| Back-door     | Damaged   | Severe   |
| Back-wheel    | No Damage | -        |
| Back-window   | No Damage | -        |
| Fender        | No Damage | -        |
| Front-door    | Damaged   | Minor    |
| Front-wheel   | No Damage | -        |
| Front-window  | No Damage | -        |
| Hood          | No Damage | -        |
| Mirror        | No Damage | -        |
| Quarter-panel | No Damage | -        |
| Rocker-panel  | No Damage | -        |

| Damage          | Severity | Raw Cost   | Covered    | Customer Pays |
|-----------------|----------|------------|------------|---------------|
| Door Outer Dent | Severe   | Rs. 19,000 | Rs. 12,000 | Rs. 7,000     |
| Door Outer Dent | Minor    | Rs. 4,000  | Rs. 2,000  | Rs. 2,000     |

# FINAL ASSESSMENT

|                        |                          |
|------------------------|--------------------------|
| Total Damage Instances | 13                       |
| Affected Vehicle Sides | FRONT, BACK, LEFT, RIGHT |
| Overall Severity       | High                     |
| Insurance Policy       | POLICY_A                 |

# FINAL BILL SUMMARY

| Description             | Amount      |
|-------------------------|-------------|
| Total Repair Cost       | Rs. 173,500 |
| Insurance Contribution  | Rs. 129,500 |
| Customer Payable Amount | Rs. 45,500  |
| Policy Type             | POLICY_A    |