

MINISTRY OF SOCIAL JUSTICE & EMPOWERMENT

Field Monitoring & Quality Inspection Sign-off Report

MoSJE FIELD INSPECTION REPORT #1

Tender: TND-2026-RD-01 - Four-Laning of Hingna Arterial Corridor

Lifecycle Status: DRAFT | Severity: NONE

Field Inspector: Rajesh M. (Inspector Nagpur)

Verifying Officer: Pending

Recorded Progress: 45.0% | Spent to Date: INR 19,800,000.00

Basis of Expenditure: Measurement Book Vol 3, p.42

Field Remarks: Initial draft measurements taken on chainage 4+200

DIGITAL EVIDENCE & GEO-LOCATION TELEMETRY

#1 [PHOTO] Lat: 21.14583, Lng: 79.08821 (Accuracy: 4.2m) | Capture Time: 1970-01-01 00:00:00

#2 [PHOTO] Lat: 21.14583, Lng: 79.08821 (Accuracy: 5.0m) | Capture Time: 1970-01-01 00:00:00

QUALITY CHECKLIST OUTCOME

Quality checklist completed without itemized exceptions.