

MINISTRY OF SOCIAL JUSTICE & EMPOWERMENT

Field Monitoring & Quality Inspection Sign-off Report

MoSJE FIELD INSPECTION REPORT #69

Tender: TND-TEST-1790283640-588 - Automated Test Bridge Repair Project

Lifecycle Status: VERIFIED | Severity: NONE

Field Inspector: Rajesh M. (Inspector Nagpur)

Verifying Officer: Virendra Deshmukh (DO Nagpur)

Recorded Progress: 70.0% | Spent to Date: INR 4,500,000.00

Basis of Expenditure: Measurement Book #101

Field Remarks: Mid-term milestone and expenditure audit

DIGITAL EVIDENCE & GEO-LOCATION TELEMETRY

#1 [PHOTO] Lat: 21.14580, Lng: 79.08820 (Accuracy: 15.5m) | Capture Time: 2026-09-24 21:00:40

QUALITY CHECKLIST OUTCOME

Quality checklist completed without itemized exceptions.