

Quarterly Compliance Pack

Period	2026-03-19 → 2026-06-17
Scope	Sydney Metro
Generated	2026-06-17T11:14:19.689360+00:00
Generated by	stephen@paneltec.com.au
Export ID	22f9dd65-38a0-41c3-920e-03d0a2e03fd1
SHA-256	586fcf07bd1f710d802685d14ac0021aee5292dd7578f8c531327857551dc96e

Swms

5 record(s) in this pack — first 50 shown.

title	status	version	created_at
Edge protection L3	draft	1	2026-06-17T04:46:26.748859+00:00
Traffic management — Erskineville tunnel	approved	1	2026-06-03T04:26:52.251815+00:00
Confined space entry — culvert C7	draft	1	2026-06-01T04:26:52.251776+00:00
Working at heights — gantry install	submitted	1	2026-05-30T04:26:52.251755+00:00
Excavation near services — Pit 14	approved	1	2026-05-28T04:26:52.251726+00:00

Pre Starts

6 record(s) in this pack — first 50 shown.

date	crew_lead	work_summary
2026-06-16	Jordan T.	Site induction refresher for 2 new sub-contractors.
2026-06-14	Jordan T.	Crew briefed on edge protection and exclusion zone. Hi-vis confirmed
2026-06-12	Jordan T.	Site induction refresher for 2 new sub-contractors.
2026-06-10	Priya S.	Crew briefed on edge protection and exclusion zone. Hi-vis confirmed
2026-06-08	Priya S.	Site induction refresher for 2 new sub-contractors.
2026-06-06	Jordan T.	Crew briefed on edge protection and exclusion zone. Hi-vis confirmed

Site Diary

5 record(s) in this pack — first 50 shown.

date	raw_notes
2026-06-16	Concrete pour started 0600, finished 1115. 25m³ delivered. Two delays — pump pri
2026-06-14	Working at heights crew on gantry install. Anchor inspection certs filed. EHS vi
2026-06-12	Concrete pour started 0600, finished 1115. 25m³ delivered. Two delays — pump pri
2026-06-10	Working at heights crew on gantry install. Anchor inspection certs filed. EHS vi
2026-06-08	Concrete pour started 0600, finished 1115. 25m³ delivered. Two delays — pump pri

Hazards

3 record(s) in this pack — first 50 shown.

title	severity	status	location
Diesel spill near generator pad	high	in_progress	Bay 3
Damaged ladder — shed	low	closed	Pit 14
Trip hazard — cable run across walkway	medium	open	Pit 14

Incidents

2 record(s) in this pack — first 50 shown.

title	category	follow_up_status	occurred_at
Property damage — fence panel struck by excavator	property	in_progress	2026-06-14T04:26:52.255106+00:00
Near miss — scaffold edge during material pass-up	near_miss	open	2026-06-12T04:26:52.255083+00:00

Inspections

3 record(s) in this pack — first 50 shown.

template_name	date
Plant inspection	2026-06-14
Working at height	2026-06-12
Site walk	2026-06-10

Contractors

8 record(s) in this pack — first 50 shown.

name	trade	status
Harbour Steel Erectors	Steel erection	active
Granite Demolition Pty Ltd	Demolition	inactive
FreshAir Ventilation	HVAC	active
Epoch Electrical	Electrical	suspended
Delta Crane Hire	Crane / Lifting	active
Civic Earthworks	Earthworks	active
BlueRock Concrete	Concrete	active
Apex Scaffolding Pty Ltd	Scaffolding	active