

**Date**

→ 2024-08-14

**Operator (Name)**

→ Stephen McGuinness

**Location**

→ Chullora Depot — 12 Waterloo Rd

**Select Vehicle**

→ H89MY — Isuzu N-Series

**Glass & Lenses — Windscreen, mirrors & light covers**☒ Pass ☐ Fail ☐ N/A**Tyres — Tread, sidewalls & air pressure**☒ Pass ☐ Fail ☐ N/A**Vehicle Panels, Bumper & Tray — Panels, bumper bar & tray free from damage**☒ Pass ☐ Fail ☐ N/A**Signs, Tools & Equipment — Speed signs, bollards, cones, weights, SSBs, all traffic control devices**☒ Pass ☐ Fail ☐ N/A**Fire Extinguisher & First Aid Kit — In date, on board, complete & accessible**☒ Pass ☐ Fail ☐ N/A**Under Bonnet Inspection — No hose wear, no oil / fluid leaks under the cab**☒ Pass ☐ Fail ☐ N/A**Seat Belts — Buckles, webbing, latch plate, retractor & pillar loop**☒ Pass ☐ Fail ☐ N/A**Globes & Alarms — Indicators, arrow boards, headlights, brake / reverse / work / flashing lights & reverse alarms**☒ Pass ☐ Fail ☐ N/A**Dashboard — Service KM/hrs, dashboard lights, no warning lights**☒ Pass ☐ Fail ☐ N/A**Cleanliness of Cab — Previous operator left cab free of rubbish**☒ Pass ☐ Fail ☐ N/A**I confirm I am in a 'Fit and Proper' state and Compliant with all Paneltec Policies prior to entering the vehicle.**☒ Pass ☐ Fail ☐ N/A**Odometer reading (km)**

→ 128,432

**Fault / Hazard — Are you submitting a Service Request or Fault Notification today?**

→ No

**Details of fault / hazard (fill in if Yes above)**☒ Pass ☐ Fail ☐ N/A**Photos of defect / service sticker / odometer (fill in if Yes above)**☒ Pass ☐ Fail ☐ N/A**Pre-Start complete**

→ Yes

Signature: \_\_\_\_\_

Date signed: 14/08/2024