


<b>Case Ref No.</b>	2026888
<b>Company</b>	Universal Sompoo
<b>Branch</b>	JAIPUR(USGI) ( 123456 )
<b>User</b>	KIRAN ( 919462283371 )
<b>User Address</b>	-
<b>App User</b>	[ US2559 ] Abhishek Vyas ( 919372750945 )
<b>Requested Date</b>	13/10/2021 16:34
<b>Inspection Date</b>	13/10/2021 17:04
<b>Inspection Completion Date</b>	13/10/2021 17:16
<b>Vcs User</b>	Aniket

Vehicle Parts		Vehicle Parts	
Wiser	Intact	Left Rear Shocker	Intact
Head Lamp	Intact	Saree Guard	Intact
Fairing	Intact	Engine Head	Intact
Front Panel	Intact	Tail Lamp	Intact
Hub Nose	Intact	Left Rear Indicator	Intact
Leg Shield	Intact	Right Rear Indicator	Intact
Mudguard	Intact	Rear Cowl	Intact
Shocker Left	Intact	Silencer	Intact
Shocker Right	Intact	Right Rear Shocker	Intact
Indicator Lt	Intact	Right Foot Rest Rear	Intact
Indicator Rt	Intact	Right Foot Rest Front	Intact
Rear View Mirror Left	Intact	Right Running Board	Intact
Rear View Mirror Right	Intact	Right Rear Cowl	Intact
Fuel Tank	Intact	Right Side Cover	Intact
Left Side Cover	Intact	Vehicle Details	
Left Running Board	Intact	Odometer Reading	5759
Left Side Rear Cowl	Intact	Chassis Number	N04305
Gear Shift Lever	Intact	Engine Number	500634
Foot Brake	Intact	Model Year	2019
Left Foot Rest Front	Intact	Color	-
Left Foot Rest Rear	Intact	Fuel Type	Petrol
Chain Cover	Intact		



**Vehicle Registration Number** RJ19BY8579


**Vehicle Type** Scooty

**Vehicle Manufacturer** Tvs Motors

**Vehicle Model** Jupiter

**Fuel Type** Petrol

**Vehicle Model Year** 2019





Client signature

I hereby confirm and declare that above mentioned identification details of my vehicle No. provided as well as that of damage to the vehicle as noted by the inspecting official are correct. Nothing has been hidden/undisclosed. I further confirm & declare that the Motor vehicle proposed for insurance after a break in cover has not met with any accident giving rise to any claim by a Third Party for injury or death caused to any person or damages to any property/Insured vehicle during the period following the expiry of a previous insurance, till the moment it is proposed for insurance. I also agree that damages mentioned above shall be excluded in the event of any claim being lodged.



(SIGNATURE)  
\*Captured on mobile screen  
Location : 26.3753762000 , 73.5361261000

QC Remarks

Vehicle details as per RC. Inspection done by Client.

\*Please note that if a vehicle body part is marked in the picture, it means it may be dented or scratched even if it is mentioned as intact in the report.  
\*We some times ask for additional pictures from the Client / Customer through Whatsapp for reference and clarification to remove any doubts. We also try and obtain a videos in many cases.





VEHICLE IMAGES



26.3753471, 73.5361686

13/10/2021 17:06

Part : FRONT SIDE  
Location : 26.3753471000 , 73.5361686000  
Date : 13/10/2021  
Time : 17:06:24



26.3753674, 73.5362053

13/10/2021 17:06

Part : LEFT SIDE  
Location : 26.3753674000 , 73.5362083000  
Date : 13/10/2021  
Time : 17:06:56



26.3753574, 73.5360862

13/10/2021 17:07

Part : ENGINE  
Location : 26.3753574000 , 73.5360862000  
Date : 13/10/2021  
Time : 17:07:10



26.3753533, 73.5361933

13/10/2021 17:09

Part : CHASIS NO.(EMBOSSSED)  
Location : 26.3753533000 , 73.5361933000  
Date : 13/10/2021  
Time : 17:09:16



26.3755265, 73.5361259

13/10/2021 17:11

Part : BACK SIDE  
Location : 26.3755265000 , 73.5361259000  
Date : 13/10/2021  
Time : 17:11:09



26.3755759, 73.5367013

13/10/2021 17:11

Part : RIGHT SIDE  
Location : 26.3755759000 , 73.5367013000  
Date : 13/10/2021  
Time : 17:11:57



VEHICLE IMAGES



<b>Part :</b> ODOMETER	<b>Date :</b> 13/10/2021
<b>Location :</b> 26.3760279000 , 73.5367434000	<b>Time :</b> 17:12:23






IMPACT IMAGES



**Part :** DAMAGED PARTS  
**Location :** 26.3753469000 , 73.5361848000  
**Date :** 13/10/2021  
**Time :** 17:12:55



SIGNATURES IMAGES

A handwritten signature in black ink on a light blue background. The signature is stylized, starting with a large loop, followed by a horizontal line, and then several vertical and curved strokes.

**Part :** CLIENT SIGNATURE  
**Location :** 26.3753762000 , 73.5361261000

**Date :** 13/10/2021  
**Time :** 17:15:41

## OTHERDOC IMAGES



Part : IMG-20211013-WA0005

Location : 0.0000000000, 0.0000000000

Date : 13/10/2021

Time : 18:00:02



Part : IMG-20211013-WA0005\_01

Location : 0.0000000000, 0.0000000000

Date : 13/10/2021

Time : 18:06:30



Part : IMG-20211013-WA0030\_01

Location : 0.0000000000, 0.0000000000

Date : 13/10/2021

Time : 18:07:19