



GNS A55

5 Nov 2025 / Eduard Cristea

Complete

Score	3 / 9 (33.33%)	Flagged items	0	Actions	0
Site conducted	Unanswered				
Conducted on	05.11.2025 06:38 GMT				
Prepared by	Eduard Cristea				
Location	772185				

A55 DETAILS

3 / 9 (33.33%)

What is the issue?

BLOCKAGE

Full Address – If Desilt or Trackwork we need to and from Address. If multiple blockages we need clear address of each

2 Hagbourne Road

What is the Surface type?**Duct type?**

PVC

Percentage of Bore Full?

Under Half (0-50%)

Number of Cables in Bore?**Is it on Private or Public Property?**

Length's between pits and blockages. These need to split into Verge, F/W, C/W

L1 – Distance in M between box/pole to blockage

60

L2 - Length (m) of blockage/trackwork required

60

L3 - Distance in M between blockage to box/pole

60

Paint mark photo of the blockage on site.

Photo 1

Chamber A**Exterior photos of chamber with context.**

Photo 2

Exterior photos of chamber with context and the pole with its DP number. – only for blockages at the pole**Photo inside of chamber.**



Photo 3

Evidence of rodding duct




Photo 4



Photo 5



Photo 6

Chamber B

Exterior photos of chamber with context.



Photo 7

Exterior photos of chamber with context and the pole with its DP number. – only for blockages at the pole

Photo inside of chamber.



Photo 8

Evidence of rodding duct



Photo 9

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9