



GNS A55

31 Oct 2025 / Eduard Cristea

Complete

Score	2 / 9 (22.22%)	Flagged items	0	Actions	0
Site conducted	Unanswered				
Conducted on	31.10.2025 09:37 GMT				
Prepared by	Eduard Cristea				
Location	772025				

A55 DETAILS

2 / 9 (22.22%)

What is the issue?

BLOCKAGE

Full Address – If Desilt or Trackwork we need to and from Address. If multiple blockages we need clear address of each

129 Broadway

What is the Surface type?**Duct type?**

PVC

Percentage of Bore Full?**Number of Cables in Bore?****Is it on Private or Public Property?**

Length's between pits and blockages. These need to split into Verge, F/W, C/W

L1 – Distance in M between box/pole to blockage

15

L2 - Length (m) of blockage/trackwork required

6p

L3 - Distance in M between blockage to box/pole

15

Paint mark photo of the blockage on site.

Photo 1

Chamber A**Exterior photos of chamber with context.**

Photo 2

Exterior photos of chamber with context and the pole with its DP number. – only for blockages at the pole**Photo inside of chamber.**



Photo 3

Evidence of rodding duct



Photo 4

Chamber B

Exterior photos of chamber with context.



Photo 5

Exterior photos of chamber with context and the pole with its DP number. – only for blockages at the pole

Photo inside of chamber.



Photo 6

Evidence of rodding duct



Photo 7

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7