

STRUCTURAL HEALTH MONITORING REPORT

Timestamp: 2026-09-06 18:40:05 | Method: Deep Learning Classification



Metric Parameter	Inspection Value
Class Diagnosis	WALL_CRACKED
Structure Element	Wall
Condition Status	DAMAGED
Confidence Score	48.85%
Severity Assessment	Collapse_risk
Safety Factor	0.00
Camera Distance	2000 mm
Focal Length	800 px

Measured Avg Width	7.169 mm
Measured Max Width	14.000 mm
Crack Length	487.5 mm
Crack Orientation	24 deg

Engineering Recommendation:

WALL EVALUATION: EMERGENCY: Evacuate area immediately. Close structure to traffic. Emergency structural assessment required. (Critical Limit: 0.3mm | Allowable Max: 1.0mm) | Measured: 7.17mm