

# STRUCTURAL HEALTH MONITORING REPORT

Timestamp: 2026-09-06 18:41:18 | Method: Deep Learning Classification



| Metric Parameter    | Inspection Value |
|---------------------|------------------|
| Class Diagnosis     | WALL_CRACKED     |
| Structure Element   | Wall             |
| Condition Status    | DAMAGED          |
| Confidence Score    | 99.95%           |
| Severity Assessment | Collapse_risk    |
| Safety Factor       | 0.00             |
| Camera Distance     | 2000 mm          |
| Focal Length        | 800 px           |

|                    |           |
|--------------------|-----------|
| Measured Avg Width | 14.201 mm |
| Measured Max Width | 21.969 mm |
| Crack Length       | 202.5 mm  |
| Crack Orientation  | 78 deg    |

***Engineering Recommendation:***

WALL EVALUATION: EMERGENCY: Evacuate area immediately. Close structure to traffic. Emergency structural assessment required. (Critical Limit: 0.3mm | Allowable Max: 1.0mm) | Measured: 14.20mm