

STRUCTURAL HEALTH MONITORING REPORT

Timestamp: 2026-09-25 23:41:06 | Method: Deep Learning Classification



Metric Parameter	Inspection Value
Class Diagnosis	PAVEMENT_CRACKED
Structure Element	Pavement
Condition Status	UNCERTAIN
Confidence Score	67.41%
Severity Assessment	Uncertain
Safety Factor	0.90
Camera Distance	2000 mm
Focal Length	800 px

Measured Avg Width	22.250 mm
Measured Max Width	31.497 mm
Crack Length	230.0 mm
Crack Orientation	61 deg

Engineering Recommendation:

PAVEMENT EVALUATION: Model confidence is low. Manual inspection and physical measurement required. Do not rely solely on AI assessment. (Critical Limit: 6.0mm | Allowable Max: 12.0mm) | Measured width 22.25mm shown for reference; severity not escalated: insufficient confidence/calibration resolution.