

Date: 11/set/26

Time: 09:27:45

Oper.: TESTE

Datatable: 2508549.DAT

Program: 2508549_120.S01

ReportNo: rept0157.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : DW6 EXH 509.613.060

Serial: 260911 0100-2

Operação: OP_120

Máquina : TESTE

Razao :TESTE

Coment:TESTE

Nome	Nominal	Mínimo Tolerancia	Máximo Tolerancia	Valor Medido	Desvio	Fora da Tol.
☒ Diametro (Inferior)						
Mancal A	35,967	-,008	,008	35,966	-,001	
Mancal B	35,967	-,008	,008	35,969	,002	
Mancal C	35,967	-,008	,008	35,960	-,007	
Mancal D	35,967	-,008	,008	35,967	,000	
Mancal E	35,967	-,008	,008	35,959	-,008	
Mancal F	35,967	-,008	,008	35,966	-,001	
Mancal G	47,967	-,008	,008	47,978#	,011	
☒ Diametro (Central)						
Mancal A	35,967	-,008	,008	35,964	-,003	
Mancal B	35,967	-,008	,008	35,972	,005	
Mancal C	35,967	-,008	,008	35,963	-,004	
Mancal D	35,967	-,008	,008	35,970	,003	
Mancal E	35,967	-,008	,008	35,961	-,006	
Mancal F	35,967	-,008	,008	35,967	,000	
Mancal G	47,967	-,008	,008	47,977#	,010	
☒ Diametro (Superior)						
Mancal A	35,967	-,008	,008	35,961	-,006	
Mancal B	35,967	-,008	,008	35,973	,006	
Mancal C	35,967	-,008	,008	35,963	-,004	
Mancal D	35,967	-,008	,008	35,970	,003	
Mancal E	35,967	-,008	,008	35,961	-,006	
Mancal F	35,967	-,008	,008	35,967	,000	
Mancal G	47,967	-,008	,008	47,977#	,010	
☒ Desvio em Relação B-C						
Mancal A	,000	,000	,120	,012	,012	
☒ Desvio em relação aos extremos						
Mancal B	,000	,000	,120	,013	,013	
Mancal C	,000	,000	,120	,031	,031	
Mancal D	,000	,000	,120	,034	,034	
Mancal E	,000	,000	,120	,031	,031	
Mancal F	,000	,000	,120	,021	,021	
☒ Desvio em relação E-F						
Mancal G	,000	,000	,120	,009	,009	
☒ Desvio em relação aos Mancais adjacentes.						
Mancal A	,000	,000	,030			
Mancal B	,000	,000	,030	,006	,006	
Mancal C	,000	,000	,030	,009	,009	
Mancal D	,000	,000	,030	,005	,005	
Mancal E	,000	,000	,030	,006	,006	
Mancal F	,000	,000	,030	,006	,006	
Mancal G	,000	,000	,030			
☒ Desvio em relação aos Mancais						
Mancal A	,000	,000	,120	,015	,015	
Mancal B	,000	,000	,120	,006	,006	
Mancal C	,000	,000	,120	,023	,023	
Mancal D	,000	,000	,120	,030	,030	
Mancal E	,000	,000	,120	,029	,029	
Mancal F	,000	,000	,120	,021	,021	
Mancal G	,000	,000	,120	,023	,023	



Model 911 SN-8609

Scania Brazil
Camshaft Measurement

Date: 11/set/26

Time: 09:27:45

Oper.: TESTE

Datatable: 2508549.DAT

Program: 2508549_120.S01

ReportNo: rept0157.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : DW6 EXH 509.613.060

Serial: 260911 0100-2

Operação: OP_120

Máquina : TESTE

Razao :TESTE

Coment:TESTE

Nome	Nominal	Mínimo Tolerancia	Máximo Tolerancia	Valor Medido	Desvio	Fora da Tol.
☒ Paralelismo Eixo						
Mancal A	,000	,000	,015	,001	,001	
Mancal B	,000	,000	,015	,001	,001	
Mancal C	,000	,000	,015	,000	,000	
Mancal D	,000	,000	,015	,000	,000	
Mancal E	,000	,000	,015	,000	,000	
Mancal F	,000	,000	,015	,001	,001	
Mancal G	,000	,000	,015	,001	,001	
☒ Cilindricidade						
Mancal A	,000	,000	,020	,006	,006	
Mancal B	,000	,000	,020	,004	,004	
Mancal C	,000	,000	,020	,003	,003	
Mancal D	,000	,000	,020	,003	,003	
Mancal E	,000	,000	,020	,003	,003	
Mancal F	,000	,000	,020	,005	,005	
Mancal G	,000	,000	,020	,002	,002	
Referencia 1 Face de Referencia						
Ângulo entre as superficies	40,000	-,125	,125	40,003	,003	
Referencia 1 Face de Referencia						
Distancia U para o Eixo de Rot	39,700	-,050	,050	39,648#	-,052	
Referencia 1 Face de Referencia						
Distancia Z para o Eixo de Rot	39,700	-,050	,050	39,676	-,024	
Raio do Circulo Base						
A1	25,000	-,100	,100	24,955	-,045	
A2	25,000	-,100	,100	24,945	-,055	
A3	25,000	-,100	,100	24,935	-,065	
A4	25,000	-,100	,100	24,929	-,071	
A5	25,000	-,100	,100	24,927	-,073	
A6	25,000	-,100	,100	24,915	-,085	
☒ Desvio do Circulo Base						
A1	,000	,000	,040	,002	,002	
A2	,000	,000	,040	,006	,006	
A3	,000	,000	,040	,002	,002	
A4	,000	,000	,040	,002	,002	
A5	,000	,000	,040	,003	,003	
A6	,000	,000	,040	,008	,008	
Concavo/Convexo						
A1	,000	-,005	,005	-,001	-,001	
A2	,000	-,005	,005	,000	,000	
A3	,000	-,005	,005	,000	,000	
A4	,000	-,005	,005	,000	,000	
A5	,000	-,005	,005	,000	,000	
A6	,000	-,005	,005	,000	,000	
☒ Paralelismo						
A1	,000	,000	,020	,001	,001	
A2	,000	,000	,020	,000	,000	
A3	,000	,000	,020	,000	,000	
A4	,000	,000	,020	,000	,000	
A5	,000	,000	,020	,000	,000	
A6	,000	,000	,020	,001	,001	



Model 911 SN-8609

Scania Brazil
Camshaft Measurement

Date: 11/set/26

Time: 09:27:45

Oper.: TESTE

Datatable: 2508549.DAT

Program: 2508549_120.S01

ReportNo: rept0157.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : DW6 EXH 509.613.060

Serial: 260911 0100-2

Operação: OP_120

Máquina : TESTE

Razao :TESTE

Coment:TESTE

Nome	Nominal	Mínimo Tolerancia	Máximo Tolerancia	Valor Medido	Desvio Fora da Tol.
☒ Angulo refer. UZ					
A1	55,500	-,100	,100	55,469	-,031
A2	175,500	-,100	,100	175,444	-,056
A3	295,500	-,100	,100	295,432	-,068
A4	115,500	-,100	,100	115,458	-,042
A5	355,500	-,100	,100	355,478	-,022
A6	235,500	-,100	,100	235,500	,000
☒ Erro Angulo para Referencia A6					
A1	180,000	-,100	,100	179,969	-,031
A2	300,000	-,100	,100	299,944	-,056
A3	60,000	-,100	,100	59,932	-,068
A4	240,000	-,100	,100	239,958	-,042
A5	120,000	-,100	,100	119,978	-,022
A6	,000	-,100	,100	,000	,000
☐ Erro de perfil do raio base					
A1	(@ 280,0) ,000	-,025	,025	,001	,001
A2	(@ 83,2) ,000	-,025	,025	-,004	-,004
A3	(@ 291,7) ,000	-,025	,025	-,001	-,001
A4	(@ 280,0) ,000	-,025	,025	,001	,001
A5	(@ 283,6) ,000	-,025	,025	-,002	-,002
A6	(@ 88,0) ,000	-,025	,025	,005	,005
☐ Erro de perfil Topo					
A1	(@ 220,0) ,000	-,100	,100	,018	,018
A2	(@ 170,7) ,000	-,100	,100	,010	,010
A3	(@ 170,7) ,000	-,100	,100	,012	,012
A4	(@ 169,7) ,000	-,100	,100	,016	,016
A5	(@ 170,9) ,000	-,100	,100	,010	,010
A6	(@ 171,7) ,000	-,100	,100	,030	,030
☐ Erro de perfil Abertura do Flanco					
A1	(@ 121,9) ,000	-,050	,050	,033	,033
A2	(@ 123,5) ,000	-,050	,050	,018	,018
A3	(@ 123,2) ,000	-,050	,050	,018	,018
A4	(@ 122,8) ,000	-,050	,050	,021	,021
A5	(@ 123,0) ,000	-,050	,050	,017	,017
A6	(@ 123,4) ,000	-,050	,050	,030	,030
☐ Erro de perfil Fechamento do Flanco					
A1	(@ 229,7) ,000	-,050	,050	,029	,029
A2	(@ 230,8) ,000	-,050	,050	,019	,019
A3	(@ 230,9) ,000	-,050	,050	,017	,017
A4	(@ 231,2) ,000	-,050	,050	,020	,020
A5	(@ 231,0) ,000	-,050	,050	,016	,016
A6	(@ 231,4) ,000	-,050	,050	,029	,029
Desvio de Velocidade					
A1	(@ 118,5) ,000	-,010	,010	,004	,004
A2	(@ 177,4) ,000	-,010	,010	-,003	-,003
A3	(@ 181,5) ,000	-,010	,010	,003	,003
A4	(@ 181,7) ,000	-,010	,010	,003	,003
A5	(@ 177,4) ,000	-,010	,010	-,003	-,003
A6	(@ 177,5) ,000	-,010	,010	-,003	-,003

ADCOLE

Model 911 SN-8609

Scania Brazil
Camshaft MeasurementDate: 11/set/26
Time: 09:27:46
Oper.: TESTEDatatable: 2508549.DAT
Program: 2508549_120.S01
ReportNo: rept0157.CAMFilter
Journal: 50 upr (Gauss)
Cam: 50 upr (Gauss)Part : DW6 EXH 509.613.060
Serial: 260911 0100-2Operação: OP_120
Máquina : TESTERazao :TESTE
Coment:TESTE

Nome	Nominal	Mínimo Tolerancia	Máximo Tolerancia	Valor Medido	Desvio Fora da Tol.		
☒ Diametro							
DM72	71,963	-,037	,037	71,958	-,005		
☒ Diametro (central)							
DM52	51,982	-,009	,009	51,982	,000		
☐ Circularidade							
DM72	,000	,000	,010	,010#	,010		
DM52	,000	,000	,010	,001	,001		
☒ Desvio em Relação F-G							
DM72	,000	,000	,020	,010	,010		
DM52	,000	,000	,020	,002	,002		



Message # 022 is for a printer form feed

Remove 4.5" Follower Tip Install 2"

Spindle R ASHOK LEYLAND lotted 0.00000

Part: 2508549.DAT

Grinder:

Date: 09/11/26

Time: 09:27:49

Journal Roundness

