

ADCOLE

Model 911 SN-8609

Scania Brazil
Camshaft Measurement

Date: 11/set/26

Time: 09:29:18

Oper.: TERSTE

Datatable: 2903706.DAT

Program: 2903706_120.S01

ReportNo: rept0121.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : 968.844.760 (DW6 EXH CRB)

Serial: 260911 0100-2

Operação: OP_120

Máquina : ESTE

Razao :TESTE

Coment:TESTE

Part: 968.844.760 (DW6 EXH CRB)

SerialNo:

Nome	Nominal	Mínimo Tolerancia	Máximo Tolerancia	Valor Medido	Desvio	Fora da Tol.
☒ Diametro (Inferior)						
Mancal A	35,967	-,008	,008	35,962	-,005	
Mancal B	35,967	-,008	,008	35,966	-,001	
Mancal C	35,967	-,008	,008	35,963	-,004	
Mancal D	35,967	-,008	,008	35,962	-,005	
Mancal E	35,967	-,008	,008	35,965	-,002	
Mancal F	35,967	-,008	,008	35,964	-,003	
Mancal G	47,967	-,008	,008	47,972	,005	
☒ Diametro (Central)						
Mancal A	35,967	-,008	,008	35,961	-,006	
Mancal B	35,967	-,008	,008	35,964	-,003	
Mancal C	35,967	-,008	,008	35,964	-,003	
Mancal D	35,967	-,008	,008	35,962	-,005	
Mancal E	35,967	-,008	,008	35,964	-,003	
Mancal F	35,967	-,008	,008	35,963	-,004	
Mancal G	47,967	-,008	,008	47,971	,004	
☒ Diametro (Superior)						
Mancal A	35,967	-,008	,008	35,958#	-,009	
Mancal B	35,967	-,008	,008	35,965	-,002	
Mancal C	35,967	-,008	,008	35,965	-,002	
Mancal D	35,967	-,008	,008	35,964	-,003	
Mancal E	35,967	-,008	,008	35,966	-,001	
Mancal F	35,967	-,008	,008	35,968	,001	
Mancal G	47,967	-,008	,008	47,969	,002	
☒ Desvio em Relação B-C						
Mancal A	,000	,000	,120	,012	,012	
☒ Desvio em relação aos extremos						
Mancal B	,000	,000	,120	,020	,020	
Mancal C	,000	,000	,120	,037	,037	
Mancal D	,000	,000	,120	,033	,033	
Mancal E	,000	,000	,120	,028	,028	
Mancal F	,000	,000	,120	,018	,018	
☒ Desvio em relação E-F						
Mancal G	,000	,000	,120	,009	,009	
☒ Desvio em relação aos Mancais adjacentes.						
Mancal A	,000	,000	,030			
Mancal B	,000	,000	,030	,006	,006	
Mancal C	,000	,000	,030	,018	,018	
Mancal D	,000	,000	,030	,004	,004	
Mancal E	,000	,000	,030	,003	,003	
Mancal F	,000	,000	,030	,005	,005	
Mancal G	,000	,000	,030			
☒ Desvio em relação aos Mancais						
Mancal A	,000	,000	,120	,026	,026	
Mancal B	,000	,000	,120	,038	,038	
Mancal C	,000	,000	,120	,048	,048	
Mancal D	,000	,000	,120	,040	,040	
Mancal E	,000	,000	,120	,028	,028	
Mancal F	,000	,000	,120	,013	,013	
Mancal G	,000	,000	,120	,014	,014	



Model 911 SN-8609

Scania Brazil
Camshaft Measurement

Date: 11/set/26

Time: 09:29:18

Oper.: TERSTE

Datatable: 2903706.DAT

Program: 2903706_120.S01

ReportNo: rept0121.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : 968.844.760 (DW6 EXH CRB)

Serial: 260911 0100-2

Operação: OP_120

Máquina : ESTE

Razao :TESTE

Coment:TESTE

Nome	Nominal	Mínimo Tolerancia	Máximo Tolerancia	Valor Medido	Desvio	Fora da Tol.
☐ Paralelismo Eixo						
Mancal A	,000	,000	,015	,0007	,0007	
Mancal B	,000	,000	,015	,0008	,0008	
Mancal C	,000	,000	,015	,0003	,0003	
Mancal D	,000	,000	,015	,0002	,0002	
Mancal E	,000	,000	,015	,0004	,0004	
Mancal F	,000	,000	,015	,0023	,0023	
Mancal G	,000	,000	,015	,0005	,0005	
☒ Cilindricidade						
Mancal A	,000	,000	,020	,0055	,0055	
Mancal B	,000	,000	,020	,0040	,0040	
Mancal C	,000	,000	,020	,0148	,0148	
Mancal D	,000	,000	,020	,0026	,0026	
Mancal E	,000	,000	,020	,0020	,0020	
Mancal F	,000	,000	,020	,0168	,0168	
Mancal G	,000	,000	,020	,0032	,0032	
Referencia 1 Face de Referencia						
Ângulo entre as superfícies	40,000	-,125	,125	40,000	,000	
Referencia 1 Face de Referencia						
Distancia U para o Eixo de Rot	39,700	-,050	,050	39,699	-,001	
Referencia 1 Face de Referencia						
Distancia Z para o Eixo de Rot	39,700	-,050	,050	39,699	-,001	
Raio do Circulo Base						
A1	25,000	-,100	,100	25,052	,052	
CRB 1	32,000	-,100	,100	32,000	,000	
A2	25,000	-,100	,100	25,041	,041	
CRB 2	32,000	-,100	,100	31,991	-,009	
A3	25,000	-,100	,100	25,047	,047	
CRB 3	32,000	-,100	,100	31,989	-,011	
A4	25,000	-,100	,100	25,047	,047	
CRB 4	32,000	-,100	,100	31,997	-,003	
A5	25,000	-,100	,100	25,054	,054	
CRB 5	32,000	-,100	,100	32,003	,003	
A6	25,000	-,100	,100	25,051	,051	
CRB 6	32,000	-,100	,100	32,002	,002	
☒ Desvio do Circulo Base						
A1	,000	,000	,040	,002	,002	
CRB 1	,000	,000	,040	,004	,004	
A2	,000	,000	,040	,003	,003	
CRB 2	,000	,000	,040	,007	,007	
A3	,000	,000	,040	,002	,002	
CRB 3	,000	,000	,040	,004	,004	
A4	,000	,000	,040	,003	,003	
CRB 4	,000	,000	,040	,004	,004	
A5	,000	,000	,040	,004	,004	
CRB 5	,000	,000	,040	,005	,005	
A6	,000	,000	,040	,001	,001	
CRB 6	,000	,000	,040	,005	,005	



Model 911 SN-8609

Scania Brazil
Camshaft MeasurementDate: 11/set/26
Time: 09:29:19
Oper.: TERSTEDatatable: 2903706.DAT
Program: 2903706_120.S01
ReportNo: rept0121.CAMFilter
Journal: 50 upr (Gauss)
Cam: 50 upr (Gauss)

Part : 968.844.760 (DW6 EXH CRB)

Serial: 260911 0100-2

Operação: OP_120

Máquina : ESTE

Razao :TESTE

Coment:TESTE

Nome	Nominal	Mínimo Tolerancia	Máximo Tolerancia	Valor Medido	Desvio Forá da Tol.	
Concavo/Convexo						
A1	,000	-,005	,005	-,0002	-,0002	
CRB 1	,000	-,005	,005	-,0002	-,0002	
A2	,000	-,005	,005	,0003	,0003	
CRB 2	,000	-,005	,005	-,0001	-,0001	
A3	,000	-,005	,005	-,0005	-,0005	
CRB 3	,000	-,005	,005	-,0002	-,0002	
A4	,000	-,005	,005	,0004	,0004	
CRB 4	,000	-,005	,005	-,0002	-,0002	
A5	,000	-,005	,005	,0003	,0003	
CRB 5	,000	-,005	,005	-,0001	-,0001	
A6	,000	-,005	,005	-,0001	-,0001	
CRB 6	,000	-,005	,005	-,0040	-,0040	
Paralelismo						
A1	,000	,000	,020	,0012	,0012	
CRB 1	,000	,000	,020	,0002	,0002	
A2	,000	,000	,020	,0008	,0008	
CRB 2	,000	,000	,020	,0002	,0002	
A3	,000	,000	,020	,0021	,0021	
CRB 3	,000	,000	,020	,0004	,0004	
A4	,000	,000	,020	,0002	,0002	
CRB 4	,000	,000	,020	,0001	,0001	
A5	,000	,000	,020	,0003	,0003	
CRB 5	,000	,000	,020	,0003	,0003	
A6	,000	,000	,020	,0026	,0026	
CRB 6	,000	,000	,020	,0158	,0158	
Angulo refer. UZ						
A1	55,500	-,100	,100	55,502	,002	
CRB 1	179,900	-,100	,100	179,885	-,015	
A2	175,500	-,100	,100	175,508	,008	
CRB 2	299,900	-,100	,100	299,903	,003	
A3	295,500	-,100	,100	295,497	-,003	
CRB 3	59,900	-,100	,100	59,906	,006	
A4	115,500	-,100	,100	115,501	,001	
CRB 4	239,900	-,100	,100	239,902	,002	
A5	355,500	-,100	,100	355,505	,005	
CRB 5	119,900	-,100	,100	119,903	,003	
A6	235,500	-,100	,100	235,487	-,013	
CRB 6	359,900	-,100	,100	359,919	,019	
Erro Angulo para Referencia A6						
A1	180,000	-,100	,100	180,015	,015	
CRB 1	304,400	-,100	,100	304,398	-,002	
A2	300,000	-,100	,100	300,021	,021	
CRB 2	64,400	-,100	,100	64,417	,017	
A3	60,000	-,100	,100	60,011	,011	
CRB 3	184,400	-,100	,100	184,420	,020	
A4	240,000	-,100	,100	240,015	,015	
CRB 4	4,400	-,100	,100	4,416	,016	
A5	120,000	-,100	,100	120,019	,019	
CRB 5	244,400	-,100	,100	244,416	,016	
A6	,000	-,100	,100	,000	,000	
CRB 6	124,400	-,100	,100	124,432	,032	



Model 911 SN-8609

Scania Brazil
Camshaft Measurement

Date: 11/set/26

Time: 09:29:19

Oper.: TERSTE

Datatable: 2903706.DAT

Program: 2903706_120.S01

ReportNo: rept0121.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : 968.844.760 (DW6 EXH CRB)

Serial: 260911 0100-2

Operação: OP_120

Máquina : ESTE

Razao :TESTE

Coment:TESTE

Nome	Nominal	Mínimo Tolerancia	Máximo Tolerancia	Valor Medido	Desvio	Fora da Tol.
☐ Erro de perfil do raio base						
A1	(@ 88,0)	,000	-,025	,025	,001	,001
CRB 1	(@ 339,3)	,000	-,025	,025	-,010	-,010
A2	(@ 85,0)	,000	-,025	,025	-,002	-,002
CRB 2	(@ 248,0)	,000	-,025	,025	-,012	-,012
A3	(@ 81,3)	,000	-,025	,025	-,001	-,001
CRB 3	(@ 247,4)	,000	-,025	,025	-,010	-,010
A4	(@ 280,0)	,000	-,025	,025	-,002	-,002
CRB 4	(@ 248,3)	,000	-,025	,025	-,010	-,010
A5	(@ 290,7)	,000	-,025	,025	-,002	-,002
CRB 5	(@ 341,5)	,000	-,025	,025	-,011	-,011
A6	(@ 280,0)	,000	-,025	,025	-,001	-,001
CRB 6	(@ 340,1)	,000	-,025	,025	-,009	-,009
☐ Erro de perfil Topo						
A1	(@ 220,0)	,000	-,100	,100	,027	,027
CRB 1	(@ 179,7)	,000	-,050	,050	-,023	-,023
A2	(@ 220,0)	,000	-,100	,100	,022	,022
CRB 2	(@ 179,8)	,000	-,050	,050	-,015	-,015
A3	(@ 220,0)	,000	-,100	,100	,022	,022
CRB 3	(@ 179,8)	,000	-,050	,050	-,012	-,012
A4	(@ 220,0)	,000	-,100	,100	,022	,022
CRB 4	(@ 179,8)	,000	-,050	,050	-,012	-,012
A5	(@ 220,0)	,000	-,100	,100	,023	,023
CRB 5	(@ 160,9)	,000	-,050	,050	,011	,011
A6	(@ 220,0)	,000	-,100	,100	,024	,024
CRB 6	(@ 179,8)	,000	-,050	,050	-,013	-,013
☐ Erro de perfil Abertura do Flanco						
A1	(@ 127,3)	,000	-,050	,050	,030	,030
A2	(@ 127,9)	,000	-,050	,050	,021	,021
A3	(@ 128,2)	,000	-,050	,050	,019	,019
A4	(@ 123,5)	,000	-,050	,050	,019	,019
A5	(@ 123,8)	,000	-,050	,050	,019	,019
A6	(@ 122,8)	,000	-,050	,050	,023	,023
☐ Erro de perfil Fechamento do Flanco						
A1	(@ 226,0)	,000	-,050	,050	,038	,038
A2	(@ 225,4)	,000	-,050	,050	,028	,028
A3	(@ 225,0)	,000	-,050	,050	,026	,026
A4	(@ 224,9)	,000	-,050	,050	,026	,026
A5	(@ 224,7)	,000	-,050	,050	,026	,026
A6	(@ 224,8)	,000	-,050	,050	,028	,028
Desvio de Velocidade						
A1	(@ 232,7)	,000	-,010	,010	-,0035	-,0035
CRB 1	(@ 181,7)	,000	-,010	,010	,0044	,0044
A2	(@ 181,5)	,000	-,010	,010	,0030	,0030
CRB 2	(@ 181,7)	,000	-,010	,010	,0039	,0039
A3	(@ 181,6)	,000	-,010	,010	,0030	,0030
CRB 3	(@ 181,5)	,000	-,010	,010	,0036	,0036
A4	(@ 177,3)	,000	-,010	,010	-,0030	-,0030
CRB 4	(@ 181,6)	,000	-,010	,010	,0035	,0035
A5	(@ 177,4)	,000	-,010	,010	-,0030	-,0030
CRB 5	(@ 181,6)	,000	-,010	,010	,0033	,0033
A6	(@ 181,5)	,000	-,010	,010	,0028	,0028
CRB 6	(@ 181,6)	,000	-,010	,010	,0036	,0036



Model 911 SN-8609

Scania Brazil
Camshaft Measurement



Date: 11/set/26
Time: 09:29:20
Oper.: TERSTE

Datatable: 2903706.DAT
Program: 2903706_120.S01
ReportNo: rept0121.CAM

Filter
Journal: 50 upr (Gauss)
Cam: 50 upr (Gauss)

Part : 968.844.760 (DW6 EXH CRB)
Serial: 260911 0100-2

Operação: OP_120
Máquina : ESTE

Razao :TESTE
Coment:TESTE

Nome	Nominal	Mínimo Tolerancia	Máximo Tolerancia	Valor Medido	Desvio Fora da Tol.		
☒ Diametro							
DM72	71,963	-,037	,037	71,967	,004		
☒ Diametro (central)							
DM52	51,982	-,009	,009	51,984	,003		
☐ Circularidade							
DM72	,000	,000	,010	,0020	,0020		
DM52	,000	,000	,010	,0026	,0026		
☒ Desvio em Relação F-G							
DM72	,000	,000	,020	,002	,002		
DM52	,000	,000	,020	,002	,002		

Check report for flags.



Message # 022 is for a printer form feed

Spindle RunOut 8609 Plotted 0.000005"/Div
Remove 4.5" Follower Tip Install 2"

Journal Roundness

