

ADCOLE Model 911 SN-8609				Scania Brazil Camshaft Measurement						SCANIA															
Date: 11/set/26 Time: 09:24:25 Oper.: TESTE				Datatable: 2960401.DAT Program: 2960401_120.S01 ReportNo: rept0067.CAM						Filter Journal: 50 upr (Gauss) Cam: 50 upr (Gauss)															
Part : PDE6 2.960.401 Serial: 260911 0100-2								Operação: OP_120 Máquina : Landis_A				Razao :Teste Coment:TESTE													
Journals																									
Max-Dia		Min-Dia		Meas-Dia		Diameter Error		Round ness		Ecc--Ref Gage		Axis Part		Runout											
Nom:				84,953																					
Tol:								,010				,070		,100											
A	84,983	84,968	84,973	,020	,0020	,018	,000	,002																	
B	84,983	84,968	84,973	,020	,0022	,025	,010	,022																	
C	84,983	84,968	84,977	,024	,0035	,030	,018	,038																	
D	84,983	84,968	84,976	,023	,0091	,029	,021	,047																	
E	84,983	84,968	84,976	,023	,0030	,025	,019	,040																	
F	84,983	84,968	84,976	,023	,0023	,014	,012	,025																	
G	84,983	84,968	84,978	,025	,0041	,003	,000	,004																	
Cams																									
Angle of cam number 1 to reference (127,500 -- 128,500) 127,863																									
		Angle Error Pino		Angle Error Cam1		-----Base Circle----- Radius Error		Runout		Velocity Error		-----Lift Error----- Nose Meas Angle		Ramp Meas Angle		-----Lift Dif----- Nose Meas Angle		Ramp Meas Angle		Center Dev.		Taper Error		Parallelism	
Nom:						31,470																			
Tol:		,250		,125		,100		,040		,010		,100		,050		,010		,010		,0200		,020		,015	
		-,250		-,125		-,100		-,040		-,010		-,100		-,050		-,010		-,010		-,0025		,020		-,015	
1	A1 EXH	,063	,000	-,062	,006	,0004	,019	140	,023	137	,0030	181	-,0025	241	-,0005	-,0034	,003								
2	D1 AUX	,150	,088	-,043	,005	,0031	,086	21	,025	21	-,0070	25	,0071	3	,0003	-,0047	,003								
3	I1 INT	,043	-,020	-,051	,006	,0003	,021	144	,025	141	,0029	181	,0020	127	-,0006	-,0007	,003								
4	A2 EXH	,048	-,015	-,053	,003	,0004	,018	140	,022	137	-,0027	177	-,0025	241	-,0010	-,0028	,003								
5	D2 AUX	,091	,028	-,058	,003	,0027	,075	21	,075#	21	-,0059	25	,0065	3	,0010	-,0030	,003								
6	I2 INT	,041	-,022	-,053	,005	,0003	,018	144	,022	141	,0030	181	,0021	126	-,0009	-,0006	,003								
7	A3 EXH	,052	-,010	-,059	,007	-,0003	,019	140	,022	137	,0031	181	,0022	123	-,0009	-,0023	,003								
8	D3 AUX	,167	,104	-,043	,007	,0026	,081	22	,080#	21	-,0057	57	,0063	3	,0000	-,0033	,003								
9	I3 INT	,031	-,031	-,062	,012	,0004	,020	173	,023	141	-,0028	177	,0018	127	-,0010	-,0003	,002								
10	A4 EXH	,031	-,032	-,056	,011	,0004	,013	140	,017	130	,0027	181	-,0022	241	-,0008	-,0019	,003								
11	D4 AUX	,110	,047	-,054	,005	,0021	,063	21	,063#	21	-,0053	25	,0056	3	-,0028#	-,0101	,001								
12	I4 INT	,048	-,014	-,055	,007	-,0004	,015	144	,017	141	,0030	181	,0016	127	-,0007	,0001	,003								
13	A5 EXH	,047	-,016	-,058	,004	-,0003	,017	140	,020	137	,0030	181	,0022	124	-,0007	-,0015	,002								
14	D5 AUX	,123	,061	-,054	,003	,0025	,076	22	,076#	21	-,0054	25	,0063	3	-,0035#	-,0091	,003								
15	I5 INT	,038	-,024	-,053	,007	-,0003	,018	144	,021	141	-,0028	177	,0019	127	-,0007	,0005	,003								
16	A6 EXH	,043	-,020	-,049	,003	,0006	,020	140	,025	131	-,0028	177	-,0027	241	-,0009	-,0010	,003								
17	D6 AUX	,174	,111	-,046	,003	,0033	,094	21	,094#	21	-,0085	25	,0074	3	-,0049#	-,0103	,003								
18	I6 INT	,044	-,019	-,054	,005	,0004	,023	144	,030	140	,0029	181	,0031	128	-,0010	,0013	,002								
Check report for flags																									

Message # 022 is for a printer form feed

Remove 4.5" Follower Tip Install 2"

Journal Roundness

Base circle radius reduced from 1.2786 to 1.2706 inches.

0 1 2 3 4