

Date: 11/set/26
Time: 09:25:17
Oper.: TESTE

Datatable: 2972987.DAT
Program: 2972987_100.S01
ReportNo: rept0071.CAM

Filter
Journal: 50 upr (Gauss)
Cam: 50 upr (Gauss)

Part : PDE5 2.972.987
Serial: 260911 0100-2

Operação: OP_100
Máquina : A1

Razao : TESTE
Coment: TESTE

Journals

	Max-Dia	Min-Dia	Meas-Dia	Diameter Error	Round ness	Ecc--Ref Gage	Axis Part	Runout
Nom:			84,953					
Tol:					,010		,070	,100
A	84,964	84,942	84,964	,011	,002	,027	,000	,002
F	84,964	84,942	84,976#	,023#	,004	,034	,000	,004

Cams

Angle of cam number 1 to reference (127,550 -- 128,050) 127,847

			-----Base Circle-----			-----Lift Error-----			-----Lift Dif-----					
	Angle Error Pino	Angle Error Cam1	Radius Error	Runout	Velocity Error	Nose Meas	Ramp Angle	Ramp Meas	Nose Meas	Ramp Angle	Ramp Meas	Center Dev.	Taper Error	Parallelism
Nom:			31,470											
Tol:	,250	,125	,100	,040	,010	,100	,050	,010	,010	,010	,020	,020	,015	
	-,250	-,125	-,100	-,040	-,010	-,100	-,050	-,010	-,010	-,010	-,003	,020	-,015	
1 A1 EXH	,047	,000	-,037	,012	-,0003	-,016	180	,013	131	,003	182	,003	125	-,0007
9 I3 INT	-89,905#	-89,952#	-1,439#	7,801#	-,0961#	7,002#	220	7,913#	232	-,293#	155	,358#	125	-,0007
15 I5 INT	144,060#	144,013#	-,051	,010	,0005	,024	144	,028	139	,003	181	,003	128	-,0002

Check report for flags.

Message # 022 is for a printer form feed

Remove 4.5" Follower Tip Install 2"

Journal Roundness

Base circle radius reduced from 1.2786 to 1.2706 inches.

