

Date: 11/set/26

Time: 09:32:59

Oper.: TESTE

Datatable: 3106033.DAT

Program: 3106033_120.S01

ReportNo: rept0370.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : Exhaust 5 IND CRB 3.106.033



Serial: 260911 0100-2

Operação: OP_120

Máquina : TESTE

Razao :TESTE

Coment:TESTE

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
☒ Diâmetro (Inferior)						
Mancal A	35,967	-,008	,008	35,959#	-,008	
Mancal B	35,967	-,008	,008	35,943#	-,024	
Mancal C	35,967	-,008	,008	35,947#	-,020	
Mancal D	35,967	-,008	,008	35,954#	-,013	
Mancal E	35,967	-,008	,008	35,965	-,002	
Mancal F	47,967	-,008	,008	47,987#	,020	
☒ Diâmetro (Central)						
Mancal A	35,967	-,008	,008	35,954#	-,013	
Mancal B	35,967	-,008	,008	35,947#	-,020	
Mancal C	35,967	-,008	,008	35,952#	-,015	
Mancal D	35,967	-,008	,008	35,946#	-,021	
Mancal E	35,967	-,008	,008	35,955#	-,012	
Mancal F	47,967	-,008	,008	47,962	-,005	
☒ Diâmetro (Central)						
DM72	71,963	-,037	,037	71,962	-,001	
DM52	51,982	-,009	,009	51,951#	-,030	
☒ Diâmetro (Superior)						
Mancal A	35,967	-,008	,008	35,953#	-,014	
Mancal B	35,967	-,008	,008	35,948#	-,019	
Mancal C	35,967	-,008	,008	35,953#	-,014	
Mancal D	35,967	-,008	,008	35,946#	-,021	
Mancal E	35,967	-,008	,008	35,954#	-,013	
Mancal F	47,967	-,008	,008	47,962	-,005	
☐ Circularidade (Central) (Processo)						
Mancal A	,000	,000	,006	,002	,002	
Mancal B	,000	,000	,006	,002	,002	
Mancal C	,000	,000	,006	,002	,002	
Mancal D	,000	,000	,006	,002	,002	
Mancal E	,000	,000	,006	,008#	,008	
Mancal F	,000	,000	,006	,002	,002	
☐ Circularidade (Central)						
DM72	,000	,000	,010	,001	,001	
DM52	,000	,000	,010	,002	,002	
☒ Desvio / A-F						
Mancal A	,000	,000	,120	,012	,012	
Mancal B	,000	,000	,120	,014	,014	
Mancal C	,000	,000	,120	,024	,024	
Mancal D	,000	,000	,120	,025	,025	
Mancal E	,000	,000	,120	,019	,019	
Mancal F	,000	,000	,120	,012	,012	
☒ Desvio / (Mancais Adjacentes)						
Mancal A	,000	,000	,030	,002	,002	
Mancal B	,000	,000	,030	,007	,007	
Mancal C	,000	,000	,030	,008	,008	
Mancal D	,000	,000	,030	,006	,006	
Mancal E	,000	,000	,030	,009	,009	
Mancal F	,000	,000	,030	,002	,002	
☒ Desvio / E-F						
DM72	,000	,000	,020	,003	,003	
DM52	,000	,000	,020	,004	,004	



Model 911 SN-8609

Scania Brazil
Camshaft Measurement

Date: 11/set/26

Time: 09:33:00

Oper.: TESTE

Datatable: 3106033.DAT

Program: 3106033_120.S01

ReportNo: rept0370.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : Exhaust 5 IND CRB 3.106.033

Serial: 260911 0100-2

Operação: OP_120

Máquina : TESTE

Razao :TESTE

Coment:TESTE

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
Desvio Circulo Base (Mancais Adjacentes)						
Exh 1	,000	,000	,040	,002	,002	
CRB 1	,000	,000	,040	,002	,002	
Exh 2	,000	,000	,040	,001	,001	
CRB 2	,000	,000	,040	,010	,010	
Exh 3	,000	,000	,040	,002	,002	
CRB 3	,000	,000	,040	,010	,010	
Exh 4	,000	,000	,040	,002	,002	
CRB 4	,000	,000	,040	,008	,008	
Exh 5	,000	,000	,040	,019	,019	
CRB 5	,000	,000	,040	,007	,007	

Paralelismo Perfil (Mancais Adjacentes)

Exh 1	,000	,000	,020	,002	,002	
CRB 1	,000	,000	,020	,002	,002	
Exh 2	,000	,000	,020	,001	,001	
CRB 2	,000	,000	,020	,002	,002	
Exh 3	,000	,000	,020	,001	,001	
CRB 3	,000	,000	,020	,003	,003	
Exh 4	,000	,000	,020	,002	,002	
CRB 4	,000	,000	,020	,003	,003	
Exh 5	,000	,000	,020	,002	,002	
CRB 5	,000	,000	,020	,004	,004	

Côncavo/Convexo

Exh 1	,000	-,025	,025	,000	,000	
CRB 1	,000	-,025	,025	,000	,000	
Exh 2	,000	-,025	,025	,000	,000	
CRB 2	,000	-,025	,025	,000	,000	
Exh 3	,000	-,025	,025	,000	,000	
CRB 3	,000	-,025	,025	,000	,000	
Exh 4	,000	-,025	,025	,000	,000	
CRB 4	,000	-,025	,025	,000	,000	
Exh 5	,000	-,025	,025	,000	,000	
CRB 5	,000	-,025	,025	,000	,000	

Paralelismo (Mancais Adjacentes)

Exh 1	,000	,000	,020	,000	,000	
CRB 1	,000	,000	,020	,000	,000	
Exh 2	,000	,000	,020	,000	,000	
CRB 2	,000	,000	,020	,000	,000	
Exh 3	,000	,000	,020	,000	,000	
CRB 3	,000	,000	,020	,002	,002	
Exh 4	,000	,000	,020	,000	,000	
CRB 4	,000	,000	,020	,001	,001	
Exh 5	,000	,000	,020	,001	,001	
CRB 5	,000	,000	,020	,002	,002	

Ângulo Referência U-Z

Exh 1	58,000	-,100	,100	57,954	-,046	
CRB 1	179,900	-,100	,100	179,871	-,029	
Exh 2	347,800	-,100	,100	347,710	-,090	
CRB 2	109,700	-,100	,100	109,613	-,087	
Exh 3	134,200	-,100	,100	134,093#	-,107	
CRB 3	256,100	-,100	,100	255,982#	-,118	
Exh 4	280,600	-,100	,100	280,482#	-,119	
CRB 4	42,500	-,100	,100	42,408	-,092	
Exh 5	210,500	-,100	,100	210,450	-,050	
CRB 5	332,400	-,100	,100	332,343	-,057	



Model 911 SN-8609

Scania Brazil
Camshaft Measurement

Date: 11/set/26

Time: 09:33:00

Oper.: TESTE

Datatable: 3106033.DAT

Program: 3106033_120.S01

ReportNo: rept0370.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : Exhaust 5 IND CRB 3.106.033

Serial: 260911 0100-2

Operação: OP_120

Máquina : TESTE

Razao :TESTE

Coment:TESTE

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
☒ Erro Ângulo para Referência A1 (Processo)						
Exh 1	,000	-,125	,125	,000	,000	
CRB 1	,000	-,125	,125	-,016	-,016	
Exh 2	,000	-,125	,125	,044	,044	
CRB 2	,000	-,125	,125	,041	,041	
Exh 3	,000	-,125	,125	,061	,061	
CRB 3	,000	-,125	,125	,073	,073	
Exh 4	,000	-,125	,125	,073	,073	
CRB 4	,000	-,125	,125	,046	,046	
Exh 5	,000	-,125	,125	,005	,005	
CRB 5	,000	-,125	,125	,011	,011	
☐ Erro de Perfil do Cículo Base						
Exh 1	,000	-,025	,025	,002	,002	
CRB 1	,000	-,025	,025	-,001	-,001	
Exh 2	,000	-,025	,025	-,001	-,001	
CRB 2	,000	-,025	,025	,005	,005	
Exh 3	,000	-,025	,025	,002	,002	
CRB 3	,000	-,025	,025	-,008	-,008	
Exh 4	,000	-,025	,025	,002	,002	
CRB 4	,000	-,025	,025	-,005	-,005	
Exh 5	,000	-,025	,025	,010	,010	
CRB 5	,000	-,025	,025	-,004	-,004	
☐ Erro de Perfil Abertura do Flanco						
Exh 1	,000	-,050	,050	,021	,021	
CRB 1	,000	-,050	,050	,016	,016	
Exh 2	,000	-,050	,050	,019	,019	
CRB 2	,000	-,050	,050	,020	,020	
Exh 3	,000	-,050	,050	,018	,018	
CRB 3	,000	-,050	,050	-,012	-,012	
Exh 4	,000	-,050	,050	,018	,018	
CRB 4	,000	-,050	,050	,014	,014	
Exh 5	,000	-,050	,050	,025	,025	
CRB 5	,000	-,050	,050	-,018	-,018	
☐ Erro de Perfil Topo						
Exh 1	,000	-,100	,100	,020	,020	
Exh 2	,000	-,100	,100	,020	,020	
Exh 3	,000	-,100	,100	,019	,019	
Exh 4	,000	-,100	,100	,021	,021	
Exh 5	,000	-,100	,100	,019	,019	
☐ Erro de Perfil Fechamento do Flanco						
Exh 1	,000	-,050	,050	,017	,017	
Exh 2	,000	-,050	,050	,014	,014	
Exh 3	,000	-,050	,050	,013	,013	
Exh 4	,000	-,050	,050	,014	,014	
Exh 5	,000	-,050	,050	,014	,014	
☐ Desvio de Velocidade						
Exh 1	,000	-,010	,010	-,002	-,002	
CRB 1	,000	-,010	,010	,003	,003	
Exh 2	,000	-,010	,010	-,003	-,003	
CRB 2	,000	-,010	,010	,004	,004	
Exh 3	,000	-,010	,010	-,003	-,003	
CRB 3	,000	-,010	,010	-,004	-,004	
Exh 4	,000	-,010	,010	-,003	-,003	
CRB 4	,000	-,010	,010	-,004	-,004	
Exh 5	,000	-,010	,010	,003	,003	
CRB 5	,000	-,010	,010	,004	,004	



