



Model 911 SN-8609

Scania Brazil
Camshaft Measurement

Date: 11/set/26

Time: 09:31:53

Oper.: TESTE

Datatable: 3070996.DAT

Program: 3070996_120.S01

ReportNo: rept1500.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : DW5 INTAKE 3.070.996

Serial: 260911 0100-2

Operação: OP_120

Máquina : TESTE

Razao :TESTE

Coment:TESTE

Part: DW5 INTAKE 3.070.996

SerialNo:

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
☒ Diameter (undre)						
Lager A	35,967	-,008	,008	35,966	-,001	
Lager B	35,967	-,008	,008	35,964	-,003	
Lager C	35,967	-,008	,008	35,962	-,005	
Lager D	35,967	-,008	,008	35,965	-,002	
Lager E	35,967	-,008	,008	35,971	,004	
Lager F nedre	47,967	-,008	,008	47,991#	,024	
Lager F övre	47,967	-,008	,008	47,990#	,023	
☒ Diameter						
D52	51,982	-,009	,009	51,983	,001	
☒ Diameter (mitten)						
Lager A	35,967	-,008	,008	35,958#	-,009	
Lager B	35,967	-,008	,008	35,963	-,004	
Lager C	35,967	-,008	,008	35,964	-,003	
Lager D	35,967	-,008	,008	35,958#	-,009	
Lager E	35,967	-,008	,008	35,962	-,005	
Lager F nedre	47,967	-,008	,008	47,965	-,002	
Lager F övre	47,967	-,008	,008	47,965	-,002	
☒ Diameter						
D72	71,963	-,037	,037	71,999	,036	
D52	51,982	-,009	,009	51,982	,001	
☒ Diameter (övre)						
Lager A	35,967	-,008	,008	35,954#	-,013	
Lager B	35,967	-,008	,008	35,961	-,006	
Lager C	35,967	-,008	,008	35,963	-,004	
Lager D	35,967	-,008	,008	35,956#	-,011	
Lager E	35,967	-,008	,008	35,961	-,006	
Lager F nedre	47,967	-,008	,008	47,965	-,002	
Lager F övre	47,967	-,008	,008	47,966	-,001	
☒ Diameter						
D52	51,982	-,009	,009	51,982	,001	
☐ Rundhet (mitten) (processmått)						
Lager A	,000	,000	,006	,002	,002	
Lager B	,000	,000	,006	,001	,001	
Lager C	,000	,000	,006	,001	,001	
Lager D	,000	,000	,006	,001	,001	
Lager E	,000	,000	,006	,001	,001	
Lager F nedre	,000	,000	,006	,002	,002	
Lager F övre	,000	,000	,006	,002	,002	
☐ Rundhet						
D72	,000	,000	,010	,001	,001	
D52	,000	,000	,010	,001	,001	
☒ Kast; mot närligande mitt						
Lager A	,000	,000	,030	,002	,002	
Lager B	,000	,000	,030	,005	,005	
Lager C	,000	,000	,030	,006	,006	
Lager D	,000	,000	,030	,011	,011	
Lager E	,000	,000	,030	,004	,004	
Lager F nedre	,000	,000	,030	,002	,002	
Lager F övre	,000	,000	,030	,002	,002	



Model 911 SN-8609

Scania Brazil
Camshaft Measurement

Date: 11/set/26

Time: 09:31:54

Oper.: TESTE

Datatable: 3070996.DAT

Program: 3070996_120.S01

ReportNo: rept1500.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : DW5 INTAKE 3.070.996

Serial: 260911 0100-2

Operação: OP_120

Máquina : TESTE

Razao :TESTE

Coment:TESTE

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
☒ Kast / mot närligande mitt						
D72	,000	,000	,020	,003	,003	
D52	,000	,000	,020	,003	,003	
☒ Kast; / A-F mitt						
Lager A	,000	,000	,120	,002	,002	
Lager B	,000	,000	,120	,010	,010	
Lager C	,000	,000	,120	,026	,026	
Lager D	,000	,000	,120	,034	,034	
Lager E	,000	,000	,120	,022	,022	
Lager F nedre	,000	,000	,120	,004	,004	
Lager F övre	,000	,000	,120	,002	,002	
☒ Kast / mot dubb (procesmått)						
Lager A	,000	,000	,050	,016	,016	
Lager B	,000	,000	,050	,015	,015	
Lager C	,000	,000	,050	,024	,024	
Lager D	,000	,000	,050	,024	,024	
Lager E	,000	,000	,050	,024	,024	
Lager F nedre	,000	,000	,050	,045	,045	
Lager F övre	,000	,000	,050	,048	,048	
D72	,000	,000	,040	,054#	,054	
D52	,000	,000	,040	,056#	,056	
☒ Parallellitet lin. profil / (mot närligande)						
Lager A	,000	,000	,015	,005	,005	
Lager B	,000	,000	,015	,005	,005	
Lager C	,000	,000	,015	,006	,006	
Lager D	,000	,000	,015	,004	,004	
Lager E	,000	,000	,015	,004	,004	
Lager F nedre	,000	,000	,015	,000	,000	
Lager F övre	,000	,000	,015	,001	,001	
☒ Parallellitet mot närligande (ej ritnings krav)						
D52	,000	,000	,020	,001	,001	
☒ Parallellitet / (över-under) (mot närligande)						
Lager A	,000	,000	,015	,000	,000	
Lager B	,000	,000	,015	,001	,001	
Lager C	,000	,000	,015	,000	,000	
Lager D	,000	,000	,015	,000	,000	
Lager E	,000	,000	,015	,000	,000	
Lager F nedre	,000	,000	,015	,000	,000	
Lager F övre	,000	,000	,015	,001	,001	
☒ Parallellitet / (över-under) (ej ritnings krav)						
D52	,000	,000	,020	,000	,000	
☒ Cyldricitet						
Lager A	,000	,000	,020	,008	,008	
Lager B	,000	,000	,020	,002	,002	
Lager C	,000	,000	,020	,002	,002	
Lager D	,000	,000	,020	,006	,006	
Lager E	,000	,000	,020	,007	,007	
Lager F nedre	,000	,000	,020	,015	,015	
Lager F övre	,000	,000	,020	,014	,014	



Model 911 SN-8609

Scania Brazil
Camshaft Measurement

Date: 11/set/26

Time: 09:31:54

Oper.: TESTE

Datatable: 3070996.DAT

Program: 3070996_120.S01

ReportNo: rept1500.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : DW5 INTAKE 3.070.996

Serial: 260911 0100-2

Operação: OP_120

Máquina : TESTE

Razao :TESTE

Coment:TESTE

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
Ref 1 Key Face						
Vinkel mellan ytorna U-Z	40,000	-,007	,007	40,002	,002	
Ref 1 Key Face						
Avstånd område U till ref.axel	39,700	-,050	,050	39,689	-,011	
Ref 1 Key Face						
Avstånd område Z till ref.axel	39,700	-,050	,050	39,707	,007	
GC Kast / mot dubb (processmått)						
A1	,000	,000	,050	,016	,016	
A2	,000	,000	,050	,019	,019	
A3	,000	,000	,050	,014	,014	
A4	,000	,000	,050	,024	,024	
A5	,000	,000	,050	,040	,040	
GC radie						
A1	25,000	-,100	,100	25,057	,057	
A2	25,000	-,100	,100	25,036	,036	
A3	25,000	-,100	,100	25,029	,029	
A4	25,000	-,100	,100	25,023	,023	
A5	25,000	-,100	,100	25,025	,025	
GC Kast / mot närligande Lager						
A1	,000	,000	,040	,003	,003	
A2	,000	,000	,040	,004	,004	
A3	,000	,000	,040	,002	,002	
A4	,000	,000	,040	,005	,005	
A5	,000	,000	,040	,019	,019	
Parallellitet lin. profil / (mot närligande)						
A1	,000	,000	,020	,006	,006	
A2	,000	,000	,020	,003	,003	
A3	,000	,000	,020	,002	,002	
A4	,000	,000	,020	,002	,002	
A5	,000	,000	,020	,002	,002	
(Konkav-Konvex)						
A1	,000	-,005	,005	,001	,001	
A2	,000	-,005	,005	,001	,001	
A3	,000	-,005	,005	,001	,001	
A4	,000	-,005	,005	,001	,001	
A5	,000	-,005	,005	,001	,001	
Parallellitet / (över-under) (mot närligande)						
A1	,000	,000	,020	,001	,001	
A2	,000	,000	,020	,001	,001	
A3	,000	,000	,020	,000	,000	
A4	,000	,000	,020	,001	,001	
A5	,000	,000	,020	,001	,001	
Vinkelfel kam till ref. U-Z						
A1	306,200	-,100	,100	306,177	-,023	
A2	236,100	-,100	,100	236,081	-,019	
A3	22,500	-,100	,100	22,481	-,019	
A4	168,900	-,100	,100	168,870	-,030	
A5	98,800	-,100	,100	98,777	-,023	



Model 911 SN-8609

Scania Brazil
Camshaft Measurement

Date: 11/set/26

Time: 09:31:55

Oper.: TESTE

Datatable: 3070996.DAT

Program: 3070996_120.S01

ReportNo: rept1500.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : DW5 INTAKE 3.070.996

Serial: 260911 0100-2

Operação: OP_120

Máquina : TESTE

Razao :TESTE

Coment:TESTE

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
☒ Vinkelfel kam till indexkam (procesmått)						
A1	,000	-,125	,125	,000	,000	
A2	,000	-,125	,125	-,004	-,004	
A3	,000	-,125	,125	-,004	-,004	
A4	,000	-,125	,125	,006	,006	
A5	,000	-,125	,125	,000	,000	
☒ Profilfel Gruncirkel						
A1	,000	-,025	,025	-,002	-,002	
A2	,000	-,025	,025	-,002	-,002	
A3	,000	-,025	,025	-,001	-,001	
A4	,000	-,025	,025	,003	,003	
A5	,000	-,025	,025	,010	,010	
☒ Profilfel Öppn						
A1	,000	-,050	,050	,033	,033	
A2	,000	-,050	,050	,025	,025	
A3	,000	-,050	,050	,024	,024	
A4	,000	-,050	,050	,025	,025	
A5	,000	-,050	,050	,032	,032	
☒ Profilfel Topp						
A1	,000	-,100	,100	,041	,041	
A2	,000	-,100	,100	,032	,032	
A3	,000	-,100	,100	,031	,031	
A4	,000	-,100	,100	,032	,032	
A5	,000	-,100	,100	,034	,034	
☒ Profilfel Stäng						
A1	,000	-,050	,050	,039	,039	
A2	,000	-,050	,050	,030	,030	
A3	,000	-,050	,050	,030	,030	
A4	,000	-,050	,050	,031	,031	
A5	,000	-,050	,050	,032	,032	
☒ Språngavvikelse						
A1	,000	,000	,010	,003	,003	
A2	,000	,000	,010	,003	,003	
A3	,000	,000	,010	,003	,003	
A4	,000	,000	,010	,003	,003	
A5	,000	,000	,010	,003	,003	













