



# Car Damage Detector & Reporter

Upload a car image...



Drag and drop file here

Limit 200MB per file • JPG, JPEG, PNG, WEBP



damaged\_car\_4.jpg 6.6KB

## Original Image



Detected Damage Highlighted



## Damage Analysis Report

Okay, let's analyze the damage visible in this image.

### Damage Description:

- **Part:** The primary damage is a significant deformation to the rear bumper of the vehicle. Specifically, it appears to be the lower portion of the bumper, likely the p
- **Severity:** The damage is *severe*. The bumper cover has been severely crushed inwards, creating a pronounced concave shape. This indicates a substantial impact

### Additional Observations:

- There is visible paint damage around the impacted area.

- The rear light is intact, indicating the damage didn't extend to the light assembly itself.

**Overall Assessment:**

This damage requires extensive repair. It's highly likely that the bumper cover needs to be replaced, and potentially the surrounding body filler as well, to properly res

**Disclaimer:** *This assessment is based solely on the image provided. A full damage assessment would require a physical inspection of the vehicle.*

Would you like me to analyze another image, or do you have any specific questions about this damage?