

Tests to be done and results:

Test Details Result DUT 1

Radiated RF Emissions (RE 310) Informative

Conducted Transient Emissions (CE 410) Compliant

RF Immunity (RI 114) Compliant

RF Immunity (RI 112) Deviation*)

Continuous Disturbance CI 210 Compliant

Transient CI 220 Deviation*)

*) Evaluation will be done by customer.

2.1 RF Immunity (RI 114)

Test 2.1.1 RF Immunity (RI 114)

DUT 1, operating mode: Standby mode 0 Nm, unit 0 rpm, 700 V

Settings:

- f: 200-1000 MHz

- E: 100 / 70 V/m

File: RI_25

Antenna: Vertical

Result: Compliant

(section end)

Test result:

The tested sample fulfilled the specifications.

No malfunction could be observed during and after the test.

2.3 RF Immunity (RI 112)

Test 2.3.1 RF Immunity (RI 112)

DUT 1, operating mode: SB

Settings:

- f: 0.1-30 MHz

- I: 90-102 dBuA

File: BCI_45

Antenna: Vertical

Result: Deviation

Signal deviation of Pressure_OTP_01_kPa and T_OTP_01_degC

4.2 Transients CI 220

Testing line: Power supply of EOBV

Test result:

The tested sample didn't fulfill the specifications.

Deviation during test with pulse C-2, E and F2.

Evaluation will be done by customer.