


VCarEA 测试报告

2026-08-17

报告概览


项目路径	D:\SCHOOL\6. 2026-Summer\Week_1\Project\EA_program\test01		
测试名称	D:\SCHOOL\6. 2026-Summer\Week_1\Project\EA_program\test01Cases\FI-05-2. case		
测试配置路径	D:\SCHOOL\6. 2026-Summer\Week_1\Project\EA_program\test01\Configurations\TestConfiguration_VCU_HIL. tcf		
测试台配置路径	D:\SCHOOL\6. 2026-Summer\Week_1\Project\EA_program\test01\Configurations\TestbenchConfiguration_VCU_HIL. tbf		
开始时间	结束时间	执行时间	
2026-08-17 10:40:57	2026-08-17 10:41:28	00:00:31.734	
测试步骤	通过步骤	失败步骤	
56	56	0	
测试用例	通过用例	失败用例	
1	1	0	

测试用例评估统计



通过：100.0000%
失败：0.0000%

测试步骤评估统计



通过：100.0000%
失败：0.0000%

FI-05-2

开始时间：2026-08-17 10:40:58.331

结束时间：2026-08-17 10:41:28.749

执行时间：30418 ms

测试步骤：56

通过步骤：56

失败步骤：0

步骤名称	开始时间	结束时间	执行时间	名称	值	评估	期望	消息	信号源	注释
StartRecorder	2026-08-17 10:40:58.348	2026-08-17 10:40:58.673	325 ms			成功		执行成功		
☐ 制动模式故障	2026-08-17 10:40:58.673	2026-08-17 10:41:28.701	30028 ms			成功		执行成功		
Write	2026-08-17 10:40:58.676	2026-08-17 10:40:58.956	280 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	100	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	制动踏板 0-100
Wait	2026-08-17 10:40:58.956	2026-08-17 10:40:59.059	103 ms		100 ms	成功		执行成功,等待100.0ms		
Write	2026-08-17 10:40:59.059	2026-08-17 10:40:59.168	109 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/Key	1	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/Key	拧钥匙 1-开 0-关
Wait	2026-08-17 10:40:59.169	2026-08-17 10:40:59.272	103 ms		100 ms	成功		执行成功,等待100.0ms		
Wait	2026-08-17 10:40:59.272	2026-08-17 10:41:02.275	3003 ms		3000 ms	成功		执行成功,等待3000.0ms		
Read	2026-08-17 10:41:02.276	2026-08-17 10:41:02.407	131 ms	[0]: env_1/网络模型/CAN/VCU/RxMsg/GW_VCU_1 (0x403)/VCU_bReadyLightSts	1.0	成功	==1	评估成功	VCU_HIL/[0]: env_1/网络模型/CAN/VCU/RxMsg/GW_VCU_1 (0x403)/VCU_bReadyLightSts	ready灯
Wait	2026-08-17 10:41:02.407	2026-08-17 10:41:02.510	103 ms		100 ms	成功		执行成功,等待100.0ms		
Write	2026-08-17 10:41:02.511	2026-08-17 10:41:02.618	107 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/Gear_Button	1	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/Gear_Button	挂D挡
Write	2026-08-17 10:41:02.619	2026-08-17 10:41:02.727	108 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/AccPedal_perc	50	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/AccPedal_perc	0到中间值 阶跃
Wait	2026-08-17 10:41:02.727	2026-08-17 10:41:02.830	103 ms		100 ms	成功		执行成功,等待100.0ms		
Write	2026-08-17 10:41:02.830	2026-08-17 10:41:02.938	108 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	0	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	松刹车
☐ 合法模式切换	2026-08-17 10:41:02.938	2026-08-17 10:41:10.234	7296 ms			成功		执行成功		

步骤名称	开始时间	结束时间	执行时间	名称	值	评估	期望	消息	信号源	注释
Write	2026-08-17 10:41:02.940	2026-08-17 10:41:03.049	109 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/AccPedal_perc	50	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/AccPedal_perc	
Wait	2026-08-17 10:41:03.049	2026-08-17 10:41:06.052	3003 ms		3000 ms	成功		执行成功,等待3000.0ms		
Write	2026-08-17 10:41:06.053	2026-08-17 10:41:06.160	107 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/AccPedal_perc	0	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/AccPedal_perc	
Wait	2026-08-17 10:41:06.160	2026-08-17 10:41:06.263	103 ms		100 ms	成功		执行成功,等待100.0ms		
Write	2026-08-17 10:41:06.263	2026-08-17 10:41:06.372	109 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakeMode	0	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait	2026-08-17 10:41:06.372	2026-08-17 10:41:06.475	103 ms		100 ms	成功		执行成功,等待100.0ms		
Write	2026-08-17 10:41:06.475	2026-08-17 10:41:06.583	108 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	50	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait	2026-08-17 10:41:06.584	2026-08-17 10:41:07.587	1003 ms		1000 ms	成功		执行成功,等待1000.0ms		
Write	2026-08-17 10:41:07.587	2026-08-17 10:41:07.695	108 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakeMode	1	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait	2026-08-17 10:41:07.696	2026-08-17 10:41:07.799	103 ms		100 ms	成功		执行成功,等待100.0ms		
Write	2026-08-17 10:41:07.799	2026-08-17 10:41:07.907	108 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	50	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait	2026-08-17 10:41:07.907	2026-08-17 10:41:08.909	1002 ms		1000 ms	成功		执行成功,等待1000.0ms		
Write	2026-08-17 10:41:08.910	2026-08-17 10:41:09.017	107 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakeMode	2	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait	2026-08-17 10:41:09.018	2026-08-17 10:41:09.121	103 ms		100 ms	成功		执行成功,等待100.0ms		

步骤名称		开始时间		结束时间		执行时间	名称	值	评估	期望	消息	信号源	注释
Write		2026-08-17 10:41:09.121	2026-08-17 10:41:09.229	108 ms			[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	50	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait		2026-08-17 10:41:09.230	2026-08-17 10:41:10.233	1003 ms				1000 ms	成功		执行成功,等待1000.0ms		
☐ 非法模式码		2026-08-17 10:41:10.234	2026-08-17 10:41:16.882	6648 ms					成功		执行成功		
Write		2026-08-17 10:41:10.236	2026-08-17 10:41:10.344	108 ms			[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/AccPedal_perc	50	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/AccPedal_perc	
Wait		2026-08-17 10:41:10.344	2026-08-17 10:41:13.347	3003 ms				3000 ms	成功		执行成功,等待3000.0ms		
Write		2026-08-17 10:41:13.347	2026-08-17 10:41:13.455	108 ms			[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/AccPedal_perc	0	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/AccPedal_perc	
Wait		2026-08-17 10:41:13.455	2026-08-17 10:41:13.558	103 ms				100 ms	成功		执行成功,等待100.0ms		
Write		2026-08-17 10:41:13.558	2026-08-17 10:41:13.666	108 ms			[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakeMode	3	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait		2026-08-17 10:41:13.666	2026-08-17 10:41:13.770	104 ms				100 ms	成功		执行成功,等待100.0ms		
Write		2026-08-17 10:41:13.770	2026-08-17 10:41:13.878	108 ms			[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	50	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait		2026-08-17 10:41:13.878	2026-08-17 10:41:16.881	3003 ms				3000 ms	成功		执行成功,等待3000.0ms		
☐ 卡死		2026-08-17 10:41:16.882	2026-08-17 10:41:22.208	5326 ms					成功		执行成功		
Write		2026-08-17 10:41:16.884	2026-08-17 10:41:16.993	109 ms			[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakeMode	0	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait		2026-08-17 10:41:16.993	2026-08-17 10:41:17.096	103 ms				100 ms	成功		执行成功,等待100.0ms		
Write		2026-08-17 10:41:17.096	2026-08-17 10:41:17.203	107 ms			[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	50	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait		2026-08-17 10:41:17.204	2026-08-17 10:41:22.207	5003 ms				5000 ms	成功		执行成功,等待5000.0ms		
☐ 跳转		2026-08-17 10:41:22.208	2026-08-17 10:41:23.475	1267 ms					成功		执行成功		

步骤名称	开始时间	结束时间	执行时间	名称	值	评估	期望	消息	信号源	注释
Write	2026-08-17 10:41:22.210	2026-08-17 10:41:22.317	107 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakeMode	0	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait	2026-08-17 10:41:22.318	2026-08-17 10:41:22.420	102 ms		100 ms	成功		执行成功,等待100.0ms		
Write	2026-08-17 10:41:22.421	2026-08-17 10:41:22.528	107 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakeMode	1	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait	2026-08-17 10:41:22.528	2026-08-17 10:41:22.630	102 ms		100 ms	成功		执行成功,等待100.0ms		
Write	2026-08-17 10:41:22.631	2026-08-17 10:41:22.738	107 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakeMode	0	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait	2026-08-17 10:41:22.739	2026-08-17 10:41:22.841	102 ms		100 ms	成功		执行成功,等待100.0ms		
Write	2026-08-17 10:41:22.841	2026-08-17 10:41:22.949	108 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakeMode	1	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait	2026-08-17 10:41:22.949	2026-08-17 10:41:23.052	103 ms		100 ms	成功		执行成功,等待100.0ms		
Write	2026-08-17 10:41:23.052	2026-08-17 10:41:23.160	108 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakeMode	0	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait	2026-08-17 10:41:23.160	2026-08-17 10:41:23.263	103 ms		100 ms	成功		执行成功,等待100.0ms		
Write	2026-08-17 10:41:23.264	2026-08-17 10:41:23.372	108 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakeMode	1	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait	2026-08-17 10:41:23.372	2026-08-17 10:41:23.474	102 ms		100 ms	成功		执行成功,等待100.0ms		
冲突 Write	2026-08-17 10:41:23.476	2026-08-17 10:41:28.700	5224 ms			成功		执行成功		
	2026-08-17 10:41:23.478	2026-08-17 10:41:23.588	110 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakeMode	1	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	

步骤名称	开始时间	结束时间	执行时间	名称	值	评估	期望	消息	信号源	注释
Write	2026-08-17 10:41:23.588	2026-08-17 10:41:23.696	108 ms	[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	0	成功		执行成功	VCU_HIL/[0]: env_1/第三方模型/Veh_1/InputPort/Veh_1/Driver/BrakePedal_perc	
Wait	2026-08-17 10:41:23.697	2026-08-17 10:41:28.699	5002 ms		5000 ms	成功		执行成功,等待5000.0ms		
StopRecorder	2026-08-17 10:41:28.702	2026-08-17 10:41:28.748	46 ms			成功		执行成功		