

2016.0 RANGE ROVER (LG), 501-12

INSTRUMENT PANEL AND CONSOLE - LONG WHEEL BASE

REAR FLOOR CONSOLE UPPER TRIM (G1699971)

REMOVAL AND INSTALLATION



REMOVAL

NOTES:

- Some components shown removed for clarity.
- Removal steps in this procedure may contain installation details.
- Some variation in the illustrations may occur, but the essential information is always correct.


1. Refer to: Rear Floor Console (501-12B, Removal and Installation).

2.




E161301

3.



E147755

4.




E148320

5.

NOTE:

Repeat the procedure for the other side.




E148323

6.

NOTE:


Repeat the procedure for the other side.



7.

CAUTION:

Make sure that the electrical harness is not trapped during the installation.




E148324

8.


NOTE:

Do not disassemble further if the component is removed for access only.




E148322

9.




10.



11.


CAUTION:

Make sure that the electrical harness is not trapped during the installation.



E148321

12.



E148325

INSTALLATION

1.

NOTE:

Install the trim retaining clips in the moulding prior to installing the components.



E149095

2. To install, reverse the removal procedure.