

2016.0 RANGE ROVER (LG), 417-01

EXTERIOR LIGHTING

SIDE TURN SIGNAL LAMP

[G1549881]

REMOVAL AND INSTALLATION

REMOVAL

NOTES:

- Removal steps in this procedure may contain installation details.
- Some variation in the illustrations may occur, but the essential information is always correct.
- LH illustration shown, RH is similar.


-
1. For additional information, refer to: [Exterior Mirror Glass](#) (501-09 Rear View Mirrors, Removal and Installation).
-

2.




E147179

3.




E147180

4.



E113600

5.



E113601

INSTALLATION

1. To install reverse the removal procedure.