Federal Public Assets Maintenance.

GENERAL REMARK (TICK ONE)

Labour operatives available	( ) Very Good	(✓) Good	( ) Fair	( ) Poor
Supply of materials on site	( ) Very Good	(✓) Good	( ) Fair	( ) Poor
Rate of progress of work	( ) Very Good	(✓) Good	( ) Fair	( ) Poor
Quality of workmanship	( ) Very Good	(✓) Good	( ) Fair	( ) Poor

Other Comments ..... SATISFACTORY .....

.....

Chief Residence Architect

Name ..... RAM PAUL TOM .....

Designation ..... PROJECT ARCHITECT (CRA) .....

Date ..... 30TH APRIL, 2024 .....

FEDERAL MINISTRY OF HOUSING AND URBAN DEVELOPMENT
HEADQUARTERS, MABUSHI, ABUJA

DEPARTMENT OF FEDERAL PUBLIC ASSETS MAINTENANCE

MONTHLY PROGRESS REPORT

CONTRACT NO: ..... LOCATION: .....

PROJECT DESCRIPTION: .....EMENT OF FEDERAL SECRETARIAT COMPLEX.....

CONTRACTOR'S NAME: M/S AIMA & COMPANY LIMITED

COMPLETION PERIOD: 5 YEARS COMMENCEMENT DATE: 07TH SEPT., 2020

FACILITY MANAGEMENT OF FEDERAL SECRETARIAT

General Cleaning of the Facility and its Surrounding ..... 100 %

Horticulture work ..... 100 %

Night Security ..... 100 %

Day Security ..... 100 %

Quarterly cleaning of Apartment ..... 100 %

Purchase of cleaning equipment ..... 100 %

Purchase of Security equipment ..... 100 %

Removal of refuse and proper disposal in a refuse dump ..... 100 %

Hiring of Staff ..... 100 %

Overall percentage of work done ..... 100 %

FEDERAL MINISTRY OF HOUSING AND URBAN DEVELOPMENT

DEPARTMENT OF FEDERAL PUBLIC ASSETS MAINTENANCE

HEADQUARTERS, MABUSHI, ABUJA, NIGERIA

FACILITY INSPECTION CHECKLIST

FACILITY DETAILS:

FACILITY	FACILITY LOCATION	INSPECTION BY:
FEDERAL SECRETARIAT COMPLEX	DAMATURU, YOBE STATE	PAM PAUL FOM
		DATE: 07TH JULY, 2023

FACILITY CONTACT PERSON	PHONE NUMBER	CONTACT DETAILS
USMAN SULEIMAN GUMBA	09061338897	NO. 49, GALADIMA ROAD POTISKUM, YOBE STATE

OKAY: YES | ACTION REQUIRED: NO | NOT APPLICABLE: N/A

SITE CONDITIONS

GATES	YES	GATEHOUSE	YES	FENCES	YES
INTERNAL ROADS	YES	SIGNAGES	YES	CAR PARKS	YES
LIGHT TOWERS/FLAG POLE	N/A	DRAINAGE	YES	DRAINAGES	YES
SUPPORT FACILITIES	N/A	KERBS	YES	FLOWERS	YES
WASTE DISPOSAL POINTS	YES	LAWN	YES	TREES	YES

BUILDING ELEMENTS

OFFICE ROOM NUMBER:

STRUCTURAL STABILITY	YES	DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	YES
LIGHTING (FITTINGS)	YES	ELECTR. (SOCKETS)	YES	ELECTR. (A.C)	YES
ELECTRICAL (CEILING FAN)	N/A	ICT (FITTINGS)	YES	CURTAIN BLINDS	YES

ROOF COVERING	YES	ROOF GUTTER	YES	PAINTING	YES

CIRCULATION AREAS:

STRUCTURAL STABILITY	YES	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	FLOOR (TILES)	YES	SOFFIT	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	YES
ELECTRICAL (CEILING FAN)	N/A	LIGHTING (FITTINGS)	YES	STAIRCASE	YES

CONVENIENCES:

DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES	WALLS	YES
WALL (TILES)	YES	FLOOR (TILES)	YES	SOFFITS	YES
WINDOWS/GLASS PANES	YES	WC	YES	WHB	YES
URINALS	YES	LIGHTING FITTINGS	YES	SHOWER	N/A

FEDERAL MINISTRY OF HOUSING AND URBAN DEVELOPMENT

DEPARTMENT OF FEDERAL PUBLIC ASSETS MAINTENANCE

HEADQUARTERS, MABUSHI, ABUJA, NIGERIA

FACILITY INSPECTION CHECKLIST

FACILITY DETAILS:

FACILITY	FACILITY LOCATION	INSPECTION BY:
FEDERAL SECRETARIAT COMPLEX	DAMATURU, YOBE STATE	PAM PAUL TOM
		DATE: 07TH APRIL 2023

FACILITY CONTACT PERSON	PHONE NUMBER	CONTACT DETAILS
USMAN SULEIMAN GIMBA	09061338897	NO. 49 GALADIMA ROAD POTISKUM, YOBE STATE

OKAY: YES | ACTION REQUIRED: NO | NOT APPLICABLE: N/A

SITE CONDITIONS

GATES	YES	GATEHOUSE	YES	FENCES	YES
INTERNAL ROADS	YES	SIGNAGES	YES	CAR PARKS	YES
LIGHT TOWERS/FLAG POLE	N/A	DRAINAGE	YES	DRAINAGES	YES
SUPPORT FACILITIES	N/A	KERBS	YES	FLOWERS	YES
WASTE DISPOSAL POINTS	YES	LAWN	YES	TREES	YES

BUILDING ELEMENTS

OFFICE ROOM NUMBER

STRUCTURAL STABILITY	YES	DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	YES
LIGHTING (FITTINGS)	YES	ELECTR. (SOCKETS)	YES	ELECTR. (A.C)	YES
ELECTRICAL (CEILING FAN)	N/A	ICT (FITTINGS)	YES	CURTAIN BLINDS	YES
ROOF COVERING	YES	ROOF GUTTER	YES	PAINTING	YES

CIRCULATION AREAS

STRUCTURAL STABILITY	YES	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	FLOOR (TILES)	YES	SOFFIT	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	YES
ELECTRICAL (CEILING FAN)	N/A	LIGHTING (FITTINGS)	YES	STAIRCASE	YES

CONVENIENCES

DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES	WALLS	YES
WALL (TILES)	YES	FLOOR (TILES)	YES	SOFFITS	YES
WINDOWS/GLASS PANES	YES	WC	YES	WHB	YES
URINALS	YES	LIGHTING FITTINGS	YES	SHOWER	N/A

FEDERAL MINISTRY OF HOUSING AND URBAN DEVELOPMENT

DEPARTMENT OF FEDERAL PUBLIC ASSETS MAINTENANCE

HEADQUARTERS, MABUSHI, ABUJA, NIGERIA

FACILITY INSPECTION CHECKLIST

FACILITY DETAILS:

FACILITY	FACILITY LOCATION	INSPECTION BY:
FEDERAL SECRETARIAT COMPLEX	DAMATURU, YOBE STATE	RAM PAUL TOM
		DATE: 07TH NOVEMBER, 2023

FACILITY CONTACT PERSON	PHONE NUMBER	CONTACT DETAILS
USMAN SULEIMAN GIMBA	09061338897	NO-49, GALADIMA ROAD, POTISKUM, YOBE STATE

OKAY: YES | ACTION REQUIRED: NO | NOT APPLICABLE: N/A

SITE CONDITIONS

GATES	YES	GATEHOUSE	YES	FENCES	YES
INTERNAL ROADS	YES	SIGNAGES	YES	CAR PARKS	YES
LIGHT TOWERS/FLAG POLE	N/A	DRAINAGE	YES	DRAINAGES	YES
SUPPORT FACILITIES	N/A	KERBS	YES	FLOWERS	YES
WASTE DISPOSAL POINTS	YES	LAWN	YES	TREES	YES

BUILDING ELEMENTS

OFFICE ROOM NUMBER

STRUCTURAL STABILITY	YES	DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	YES
LIGHTING (FITTINGS)	YES	ELECTR. (SOCKETS)	YES	ELECTR. (A.C)	YES
ELECTRICAL (CEILING FAN)	N/A	ICT (FITTINGS)	YES	CURTAIN BLINDS	YES
ROOF COVERING	YES	ROOF GUTTER	YES	PAINTING	YES

CIRCULATION AREAS

STRUCTURAL STABILITY	YES	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	FLOOR (TILES)	YES	SOFFIT	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	YES
ELECTRICAL (CEILING FAN)	N/A	LIGHTING (FITTINGS)	YES	STAIRCASE	YES

CONVENIENCES

DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES	WALLS	YES
WALL (TILES)	YES	FLOOR (TILES)	YES	SOFFITS	YES
WINDOWS/GLASS PANES	YES	WC	YES	WHB	YES
URINALS	YES	LIGHTING FITTINGS	YES	SHOWER	YES

FEDERAL MINISTRY OF HOUSING AND URBAN DEVELOPMENT

DEPARTMENT OF FEDERAL PUBLIC ASSETS MAINTENANCE

HEADQUARTERS, MABUSHI, ABUJA, NIGERIA

FACILITY INSPECTION CHECKLIST

FACILITY DETAILS:

FACILITY	FACILITY LOCATION	INSPECTION BY:
FEDERAL SECRETARIAT COMPLEX	DAMATURU, YOBE STATE.	RAM PAUL FOM
		DATE: 07TH OCTOBER, 2023

FACILITY CONTACT PERSON	PHONE NUMBER	CONTACT DETAILS
USMAN SULEIMAN GMBA	09061338897	NO. 43 GALADIMA ROAD, POTISKUM, YOBE STATE

OKAY: YES | ACTION REQUIRED: NO | NOT APPLICABLE: N/A

SITE CONDITIONS

GATES	YES	GATEHOUSE	YES	FENCES	YES
INTERNAL ROADS	YES	SIGNAGES	YES	CAR PARKS	YES
LIGHT TOWERS/FLAG POLE	N/A	DRAINAGE	YES	DRAINAGES	YES
SUPPORT FACILITIES	N/A	KERBS	YES	FLOWERS	YES
WASTE DISPOSAL POINTS	YES	LAWN	YES	TREES	YES

BUILDING ELEMENTS

OFFICE ROOM NUMBER

STRUCTURAL STABILITY	YES	DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	YES
LIGHTING (FITTINGS)	YES	ELECTR. (SOCKETS)	YES	ELECTR. (A.C)	YES
ELECTRICAL (CEILING FAN)	N/A	ICT (FITTINGS)	YES	CURTAIN BLINDS	YES
ROOF COVERING	YES	ROOF GUTTER	YES	PAINTING	YES

CIRCULATION AREAS

STRUCTURAL STABILITY	YES	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	FLOOR (TILES)	YES	SOFFIT	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	YES
ELECTRICAL (CEILING FAN)	N/A	LIGHTING (FITTINGS)	YES	STAIRCASE	YES

CONVENIENCES

DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES	WALLS	YES
WALL (TILES)	YES	FLOOR (TILES)	YES	SOFFITS	YES
WINDOWS/GLASS PANES	YES	WC	YES	WHB	YES
URINALS	YES	LIGHTING FITTINGS	YES	SHOWER	YES