FEDERAL MINISTRY OF WORKS AND HOUSING

DEPARTMENT OF FEDERAL PUBLIC ASSETS MAINTENANCE

HEADQUARTERS, MABUSHI, ABUJA, NIGERIA

FACILITY INSPECTION CHECKLIST

FACILITY DETAILS:

FACILITY	FACILITY LOCATION	INSPECTION BY:	
FEDERA SECRETARIAT YOLA, ADAMAWA	ADAMAWA STATE	M. AHEED SHEHU	
		DATE	20TH MARCH, 2025

FACILITY CONTACT PERSON	PHONE NUMBER	CONTACT DETAILS
MOHAMMED M. YAHAYA	8033924174	43, ATIKU ABUBAKAR WAY, JIMETA, YOLA

OKAY	YES	ACTION REQUIRED	NO	NOT APPLICABLE	N/A

SITE CONDITIONS

GATES	YES	GATEHOUSE	YES	FENCES	YES
INTERNAL ROADS	YES	SIGNAGES	N/A	CAR PARKS	YES
LIGHT TOWERS/FLAG POLE	YES	DRAINAGE	YES	DRAINAGES	YES
SUPPORT FACILITIES	YES	KERBS	N/A	FLOWERS	YES
WASTE DISPOSAL POINTS	YES	LAWN	YES	TREES	YES

BUILDING ELEMENTS

OFFICE ROOM NUMBER

STRUCTURAL STABILITY	N/A	DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	YES
LIGHTING (FITTINGS)	YES	ELECTR. (SOCKETS)	YES	ELECTR. (A.C)	YES
ELECTRICAL (CEILING FAN)	YES	ICT (FITTINGS)	N/A	CURTAIN BLINDS	YES
ROOF COVERING	N/A	ROOF GUTTER	YES	PAINTING	YES

CIRCULATION AREAS

STRUCTURAL STABILITY	N/A	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	FLOOR (TILES)	YES	SOFFIT	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	YES
ELECTRICAL (CEILING FAN)	YES	LIGHTING (FITTINGS)	YES	STAIRCASE	YES

CONVENIENCES

DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES	WALLS	YES
WALL (TILES)	YES	FLOOR (TILES)	YES	SOFFITS	YES
WINDOWS/GLASS PANES	YES	WC	YES	WHB	YES
URINALS	YES	LIGHTING FITTINGS	YES	SHOWER	YES

FEDERAL MINISTRY OF WORKS AND HOUSING (HOUSING)

HEADQUARTERS, MABUSHI, ABUJA

FEDERAL PUBLIC ASSETS MAINTENANCE DEPARTMENT

PROGRESS REPORT

CONTRACT NO: FMW&H/DPP/1ST MTB/2020/2861 Vol.I/33 LOCATION: ADAMAWA STATE

PROJECT DESCRIPTION: CONTRACT FOR THE FACILITY MANAGEMENT OF THE FEDERAL SECRETARIAT COMPLEX, YOLA ADAMAWA

CONTRACTOR'S NAME: M/S PRUDENTIAL NORTHERN STARS LIMITED

COMPLETION PERIOD: 20TH MARCH 2025 COMMENCEMENT DATE: 20TH FEBRUARY 2025

PROGRESS OF WORK

FACILITY MANAGEMENT OF THE FEDERAL SECRETARIAT COMPLEX.

1. General Cleaning of the Complex and its surroundings..... 100%
2. Horticulture.....100%
3. Provision of Adequate Security.....100%
4. Attendance to Minor Mechanical repairs.....100%
5. Ensuring of continuous flow of water.....100%
6. Attendance to minor electrical repairs.....100%
7. Operation, servicing of generator & Borehole.....100%

1) Director, Federal Public Assests Maintenance.
2) Deputy Director, Monitoring and Evaluation
3) The Controller, Field Headquarters.
4) Chief Resident Architect.

8. Minor repairs of doors & windows.....100%

9. Fumigation of the complex.....100%

10. Removal of Refuse.....100%

11. Overall percentage work done.....100%

GENERAL REMARK (TICK ONE)

Labour operatives available ( ) Very Good (✓) Good ( ) Fair ( ) Poor

Supply of Material on site ( ) Very Good (✓) Good ( ) Fair ( ) Poor

Rate of progress of work (✓) Very Good ( ) Good ( ) Fair ( ) Poor

Quality of Workmanship ( ) Very Good (✓) Good ( ) Fair ( ) Poor

Other Comment: **WORK DONE PROFESSIONALLY**

.....

.....

.....

CHIEF RESIDENT ARCHITECT FMW&H.

NAME: **M. AHEED SHEHU**

DESIGNATION: **ASSISTANT DIRECTOR**

DATE: **20TH MARCH 2025.**

FEDERAL MINISTRY OF WORKS AND HOUSING

DEPARTMENT OF FEDERAL PUBLIC ASSETS MAINTENANCE

HEADQUARTERS, MABUSHI, ABUJA, NIGERIA

FACILITY INSPECTION CHECKLIST

FACILITY DETAILS:

FACILITY	FACILITY LOCATION	INSPECTION BY:	
FEDERA SECRETARIAT YOLA, ADAMAWA	ADAMAWA STATE	M. AHEED SHEHU	
		DATE	20TH APRIL, 2025

FACILITY CONTACT PERSON	PHONE NUMBER	CONTACT DETAILS
MOHAMMED M. YAHAYA	8033924174	43, ATIKU ABUBAKAR WAY, JIMETA, YOLA

OKAY	YES	ACTION REQUIRED	NO	NOT APPLICABLE	N/A

SITE CONDITIONS

GATES	YES	GATEHOUSE	YES	FENCES	YES
INTERNAL ROADS	YES	SIGNAGES	N/A	CAR PARKS	YES
LIGHT TOWERS/FLAG POLE	YES	DRAINAGE	YES	DRAINAGES	YES
SUPPORT FACILITIES	YES	KERBS	N/A	FLOWERS	YES
WASTE DISPOSAL POINTS	YES	LAWN	YES	TREES	YES

BUILDING ELEMENTS

OFFICE ROOM NUMBER

STRUCTURAL STABILITY	N/A	DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	YES
LIGHTING (FITTINGS)	YES	ELECTR. (SOCKETS)	YES	ELECTR. (A.C)	YES
ELECTRICAL (CEILING FAN)	YES	ICT (FITTINGS)	N/A	CURTAIN BLINDS	YES
ROOF COVERING	N/A	ROOF GUTTER	YES	PAINTING	YES

CIRCULATION AREAS

STRUCTURAL STABILITY	N/A	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	FLOOR (TILES)	YES	SOFFIT	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	YES
ELECTRICAL (CEILING FAN)	YES	LIGHTING (FITTINGS)	YES	STAIRCASE	YES

CONVENIENCES

DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES	WALLS	YES
WALL (TILES)	YES	FLOOR (TILES)	YES	SOFFITS	YES
WINDOWS/GLASS PANES	YES	WC	YES	WHB	YES
URINALS	YES	LIGHTING FITTINGS	YES	SHOWER	YES

FEDERAL MINISTRY OF WORKS AND HOUSING (HOUSING)

HEADQUARTERS, MABUSHI, ABUJA

FEDERAL PUBLIC ASSETS MAINTENANCE DEPARTMENT

PROGRESS REPORT

CONTRACT NO: FMW&H/DPP/1ST MTB/2020/2861 Vol.I/33 LOCATION: ADAMAWA STATE

PROJECT DESCRIPTION: CONTRACT FOR THE FACILITY MANAGEMENT OF THE FEDERAL SECRETARIAT COMPLEX, YOLA ADAMAWA

CONTRACTOR'S NAME: M/S PRUDENTIAL NORTHERN STARS LIMITED

COMPLETION PERIOD: 20TH APRIL 2025 COMMENCEMENT DATE: 20TH MARCH 2025

PROGRESS OF WORK

FACILITY MANAGEMENT OF THE FEDERAL SECRETARIAT COMPLEX.

1. General Cleaning of the Complex and its surroundings..... 100%
2. Horticulture.....100%
3. Provision of Adequate Security.....100%
4. Attendance to Minor Mechanical repairs.....100%
5. Ensuring of continuous flow of water.....100%
6. Attendance to minor electrical repairs.....100%
7. Operation, servicing of generator & Borehole.....100%

1) Director, Federal Public Assests Maintenance.
2) Deputy Director, Monitoring and Evaluation
3) The Controller, Field Headquarters.
4) Chief Resident Architect.

8. Minor repairs of doors & windows.....100%

9. Fumigation of the complex.....100%

10. Removal of Refuse.....100%

11. Overall percentage work done.....100%

GENERAL REMARK (TICK ONE)

Labour operatives available ( ) Very Good (✓) Good ( ) Fair ( ) Poor

Supply of Material on site ( ) Very Good (✓) Good ( ) Fair ( ) Poor

Rate of progress of work ( ) Very Good (✓) Good ( ) Fair ( ) Poor

Quality of Workmanship ( ) Very Good (✓) Good ( ) Fair ( ) Poor

Other Comment: **WORK DONE PROFESSIONALLY**

.....

.....

.....

CHIEF RESIDENT ARCHITECT FMH&UD.

NAME: **M. AHEED SHEHU**

DESIGNATION: **ASSISTANT DIRECTOR**

DATE: **20TH APRIL 2025.**