FEDERAL MINISTRY OF WORKS AND HOUSING

DEPARTMENT OF FEDERAL PUBLIC ASSETS MAINTENANCE

HEADQUARTERS, MABUSHI, ABUJA, NIGERIA

FACILITY INSPECTION CHECKLIST

FACILITY DETAILS:

FACILITY .	FACILITY LOCATION	INSPECTION BY:
NATIONAL HOUSING PROGRAMME, PHASE 2	NSUKKA ENUGU STATE	ARC F. OKEREKE
		DATE

FACILITY CONTACT PERSON	PHONE NUMBER	CONTACT DETAILS
MR DANJUMA EZRA	07054607031	NHP, NSUKKA

OKAY: YES | ACTION REQUIRED: NO | NOT APPLICABLE: N/A

SITE CONDITIONS

GATES	N/A	GATEHOUSE	N/A	FENCES	N/A
INTERNAL ROADS	YES	SIGNAGES	N/A	CAR PARKS	N/A
LIGHT TOWERS/FLAG POLE	YES	DRAINAGE	YES	DRAINAGES	YES
SUPPORT FACILITIES	YES	KERBS	YES	FLOWERS	N/A
WASTE DISPOSAL POINTS	YES	LAWN	YES	TREES	YES

BUILDING ELEMENTS

OFFICE ROOM NUMBER: 2 BEDROOMS

STRUCTURAL STABILITY	YES	DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	YES
LIGHTING (FITTINGS)	YES	ELECTR. (SOCKETS)	YES	ELECTR. (A.C)	YES
ELECTRICAL (CEILING FAN)	YES	ICT (FITTINGS)	N/A	CURTAIN BLINDS	YES
ROOF COVERING	YES	ROOF GUTTER	YES	PAINTING	YES

CIRCULATION AREAS: LOBBIES, PORCHES, STOURS

STRUCTURAL STABILITY	YES	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	FLOOR (TILES)	YES	SOFFIT	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	YES
ELECTRICAL (CEILING FAN)	YES	LIGHTING (FITTINGS)	YES	STAIRCASE	YES

CONVENIENCES: TOILETS, BATHROOMS, KITCHEN

DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES	WALLS	YES
WALL (TILES)	YES	FLOOR (TILES)	YES	SOFFITS	YES
WINDOWS/GLASS PANES	YES	WC	YES	WHB	YES
URINALS	YES	LIGHTING FITTINGS	YES	SHOWER	YES

FEDERAL MINISTRY OF WORKS AND HOUSING

DEPARTMENT OF FEDERAL PUBLIC ASSETS MAINTENANCE

HEADQUARTERS, MABUSHI, ABUJA, NIGERIA

FACILITY INSPECTION CHECKLIST

FACILITY DETAILS:

FACILITY	FACILITY LOCATION	INSPECTION BY:
NATIONAL HOUSING PROGRAMME 2	NSUKKA, ENUGU STATE	ARC E. OKEREKE
		DATE: 20/04/2024

FACILITY CONTACT PERSON	PHONE NUMBER	CONTACT DETAILS
MR UCHE AUSTIN	08033361079	NHP 2, NSUKKA

OKAY: YES | ACTION REQUIRED: NO | NOT APPLICABLE: N/A

SITE CONDITIONS

GATES	N/A	GATEHOUSE	N/A	FENCES	N/A
INTERNAL ROADS	YES	SIGNAGES	N/A	CAR PARKS	N/A
LIGHT TOWERS/FLAG POLE	YES	DRAINAGE	YES	DRAINAGES	YES
SUPPORT FACILITIES	YES	KERBS	YES	FLOWERS	N/A
WASTE DISPOSAL POINTS	YES	LAWN	YES	TREES	YES

BUILDING ELEMENTS

OFFICE ROOM NUMBER: 2 BEDROOMS

STRUCTURAL STABILITY	YES	DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	YES
LIGHTING (FITTINGS)	YES	ELECTR. (SOCKETS)	YES	ELECTR. (A.C)	YES
ELECTRICAL (CEILING FAN)	YES	ICT (FITTINGS)	YES	CURTAIN BLINDS	YES
ROOF COVERING	YES	ROOF GUTTER		PAINTING	YES

CIRCULATION AREAS: LOBBIES, PORCHES, SIT OUTS

STRUCTURAL STABILITY	YES	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	FLOOR (TILES)	YES	SOFFIT	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	YES
ELECTRICAL (CEILING FAN)	YES	LIGHTING (FITTINGS)	YES	STAIRCASE	YES

CONVENIENCES: TOILETS, BATHROOMS & KITCHEN

DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES	WALLS	YES
WALL (TILES)	YES	FLOOR (TILES)	YES	SOFFITS	YES
WINDOWS/GLASS PANES	YES	WC	YES	WHB	YES
URINALS	YES	LIGHTING FITTINGS	YES	SHOWER	YES

FEDERAL MINISTRY OF POWER, WORKS AND HOUSING (HOUSING SECTOR)
HEADQUARTERS, MABUSHI, ABUJA
DEPARTMENT OF FEDERAL PUBLIC ASSETS MAINTENANCE.

PROGRESS REPORT

CONTRACT NO: FMWH/FPAM/2022/03/1125 LOCATION: NSUKKA, ENUGU STATE

PROJECT DESCRIPTION: FACILITY MAGEMENT OF NATIONAL HOUSING PROGRAMME(NHP) ESTATE, PHASE 2

CONTRACTOR'S NAME: MESSERS: GECHNDO LTD

COMPLETION PERIOD: 12 MONTHS COMMENCEMENT DATE: 18/04/2023

FACILITY MANAGEMENT OF FEDERAL SECRETARIAT

1) General Cleaning of the Complex and its Surrounding..... 100 %
2) Horticulture work..... 100 %
3) Attendance to Minor Mechanical repairs in the complex ..... 100 %
4) Water supply in the Complex for Improved sanitation purposes ..... 100 %
5) Attendance to minor Electrical repairs..... 90 %
6) Operation, servicing of generators and minor repairs of borehole..... 80 %
7) Quarterly fumigation of the complex ..... 80 %
8) Removal of refuse and proper disposal in a refuse dump..... 100 %
9) Provision of equipment, tools and non-hazardous chemical..... 100 %
10) Minor repairs of doors and windows such as locks and hinges..... 100 %
11) Overall percentage of work done..... 85 %

GENERAL REMARK (TICK ONE)

Labour operatives available	(✓) Very Good ( ) Good ( ) Fair ( ) Poor
Supply of materials on site	( ) Very Good (✓) Good ( ) Fair ( ) Poor
Rate of progress of work	( ) Very Good (✓) Good ( ) Fair ( ) Poor
Quality of Workmanship	(✓) Very Good ( ) Good ( ) Fair ( ) Poor

Other Comments..... Job well done !

.....

Chief Residence Architect
Name..... ARC Ejikeme Okereke
Designation..... Senior Architect
Date..... 25/04/2024

DISTRIBUTION:

1. Director/HOD, Federal Public Asset Maintenance
2. Deputy Director M&E
3. The Controller, Field Headquarter
4. Chief Project Architect