FEDERAL MINISTRY OF HOUSING AND URBAN DEVELOPMENT

DEPARTMENT OF FEDERAL PUBLIC ASSETS MAINTENANCE

HEADQUARTERS, MABUSHI, ABUJA, NIGERIA

FACILITY INSPECTION CHECKLIST

FACILITY DETAILS:

FACILITY	FACILITY LOCATION	INSPECTION BY:
NATIONAL HOUSING ESTATE PHASE II, ~~ABERE~~, OGUN STATE	~~ABERE~~, OGUN STATE	Arc. Sebastine Abang
		DATE 13/10/2025

FACILITY CONTACT PERSON	PHONE NUMBER	CONTACT DETAILS
	08023321270	FIELD HQ, OKEFIA, OGUN STATE

OKAY	YES	ACTION REQUIRED	NO	NOT APPLICABLE	N/A

SITE CONDITIONS

GATES	N/A	GATEHOUSE	N/A	FENCES	N/A
INTERNAL ROADS	YES	SIGNAGES	NO	CAR PARKS	N/A
LIGHT TOWERS/FLAG POLE	YES	DRAINAGE	YES	DRAINAGES	YES
SUPPORT FACILITIES	YES	KERBS	YES	FLOWERS	N/A
WASTE DISPOSAL POINTS	N/A	LAWN	NO	TREES	YES

BUILDING ELEMENTS

OFFICE ROOM NUMBER

STRUCTURAL STABILITY	N/A	DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	NO
FLOOR (TILES)	NO	SOFFIT	YES	ELECTR. (SWITCH)	NO
LIGHTING (FITTINGS)	NO	ELECTR. (SOCKETS)	NO	ELECTR. (A.C)	NO
ELECTRICAL (CEILING FAN)	NO	ICT (FITTINGS)	NO	CURTAIN BLINDS	No

ROOF COVERING	NO	ROOF GUTTER	NO	PAINTING	NO

CIRCULATION AREAS

STRUCTURAL STABILITY	N/A	WALLS(EXTERNAL)	YES	WALLS(INTERNAL)	YES
WINDOWS/GLASS PANES	YES	FLOOR (TILES)	NO	SOFFIT	YES
FLOOR (TILES)	YES	SOFFIT	YES	ELECTR. (SWITCH)	NO
ELECTRICAL (CEILING FAN)	NO	LIGHTING (FITTINGS)	NO	STAIRCASE	NO

CONVENIENCES

DOORS(EXTERNAL)	YES	DOORS(INTERNAL)	YES	WALLS	YES
WALL (TILES)	NO	FLOOR (TILES)	NO	SOFFITS	YES
WINDOWS/GLASS PANES	NO	WC	NO	WHB	NO
URINALS	NO	LIGHTING FITTINGS	NO	SHOWER	NO

FEDERAL MINISTRY OF HOUSING AND URBAN DEVELOPMENT

HEADQUARTERS, MABUSHI, ABUJA

DEPARTMENT OF FEDERAL PUBLIC ASSETS MAINTENANCE.

MONTHLY PROGRESS REPORT

CONTRACT NO: FMHUD/FPAM/2024/05/1/28 ..... LOCATION: ABERE, OSUN STATE

PROJECT DESCRIPTION: FACILITY MANAGEMENT OF NATIONAL HOUSING PROGRAMME (NHP) ESTATE, PHASE II

CONTRACTOR'S NAME: MESSRS TAKBOF BUSINESS LINK LTD

COMPLETION PERIOD: 12 MONTHS ..... COMMENCEMENT DATE: 10-07-2025

FACILITY MANAGEMENT OF FEDERAL SECRETARIAT

General Cleaning of the Facility and its Surrounding ..... 100 ..... %

Horticulture work ..... 100 ..... %

Night Security ..... 100 ..... %

Day Security ..... 100 ..... %

Quarterly cleaning of Apartment ..... 100 ..... %

Purchase of cleaning equipment ..... 100 ..... %

Purchase of Security equipment ..... 100 ..... %

Removal of refuse and proper disposal in a refuse dump ..... 100 ..... %

Hiring of Staff ..... 100 ..... %

Overall percentage of work done ..... 100 ..... %

GENERAL REMARK (TICK ONE)

Labour operatives available	(✓) Very Good ( ) Good ( ) Fair ( ) Poor
Supply of materials on site	( ) Very Good (✓) Good ( ) Fair ( ) Poor
Rate of progress of work	(✓) Very Good ( ) Good ( ) Fair ( ) Poor
Quality of Workmanship	(✓) Very Good ( ) Good ( ) Fair ( ) Poor

Other Comments Services executed satisfactorily

13/10/2025

Chief Residence Architect

Name Sebastine Abang

Designation Chief Resident Architect

Date 13-10-2025

DISTRIBUTION:

1. Director/HOD, Federal Public Asset Maintenance
2. Deputy Director M&E
3. The Controller, Field Headquarter
4. Chief Project Architect

Federal Public Assets Maintenance.