


Machinery QA Inspection Report


Machine: Machine A


Shift: Morning

Date: 2025-09-19

Status: Pass

 Temperature: 23.0 (Spec: 20-30)

 Pressure: 150.0 (Spec: 100-200)

 Vibration: 5.0 (Spec: 0-5)

AI Inspection Suggestions:

No AI suggestions available due to missing API key.