

Mahanadi Coalfields Limited - Environmental Compliance Report FY 2022-23

CMPDI / Coal India Limited - Confidential Internal Document

Section 1: Environmental Clearances Status

Mahanadi Coalfields Limited (MCL) Environmental Compliance Report for FY 2022-23.

Environmental Clearance (EC) Status - All Active MCL Mines:

Key EC details:

Ib Valley Coalfields (Odisha):

No material non-compliance under the Environment Protection Act, 1986 was recorded during FY 2022-23.

Section 2: Air Quality and Dust Management

Ambient Air Quality Monitoring - FY 2022-23:

MCL operates 38 ambient air quality monitoring stations across all coalfield areas as per CPCB norms.

Aggregate annual average values (MCL coalfields):

PM10 exceedance analysis:

Compliance status: Under MoEFCC Consent to Operate conditions, quarterly monitoring reports

Section 3: Water Management and Land Reclamation

Water Management - MCL FY 2022-23:

Mine water discharge:

Water quality parameters at discharge points:

Land Reclamation:

Progressive mine closure: