

Return & Warranty Claim Form - BW-88213

BOXWOOD RETURNS - RETURN & WARRANTY CLAIM FORM

Order #: BW-88213

Item: Canvas tote bag - Olive

Quantity: 1

Reason: ☒ Damaged ☐ Wrong item ☐ Changed mind

Defect description: Strap seam torn near the buckle

Defect location: Left strap

Photos attached: Yes (2)

Purchase date: 08/14/2026

Buyer tier: Pro member

Requested resolution: Replacement

Customer signature: (signed)