

Building Health Inspection Report


Frontwall Wall



Backwall Wall



Leftwall Wall



Rightwall Wall



AI-Based Risk Analysis

AI-Based Structural Crack Analysis:

Overall Average Score (out of 10): 5.6

- Frontwall Wall: 5.5/10
- Backwall Wall: 8.5/10
- Leftwall Wall: 0.0/10
- Rightwall Wall: 8.5/10

Severity Level: Medium

Recommendation: Monitor the structure and consider a professional inspection.