


# Building Health Inspection Report

## Frontwall Wall



## Backwall Wall



**Leftwall Wall**



**Rightwall Wall**



**AI-Based Risk Analysis**

## AI-Based Structural Crack Analysis:

Overall Average Score (out of 10): 9.2

- Frontwall Wall: 7.0/10
- Backwall Wall: 10.0/10
- Leftwall Wall: 10.0/10
- Rightwall Wall: 10.0/10

Severity Level: Low

Recommendation: Structure is likely healthy. No immediate action needed.