


Building Health Inspection Report

Frontwall Wall




Backwall Wall



Leftwall Wall



Rightwall Wall



AI-Based Risk Analysis

AI-Based Structural Crack Analysis:

Overall Average Score (out of 10): 8.1

- Frontwall Wall: 10.0/10
- Backwall Wall: 10.0/10
- Leftwall Wall: 5.5/10
- Rightwall Wall: 7.0/10

Severity Level: Low

Recommendation: Structure is likely healthy. No immediate action needed.