


# Building Health Inspection Report

## Frontwall Wall



## Backwall Wall



**Leftwall Wall**



**Rightwall Wall**





## AI-Based Risk Analysis

AI-Based Structural Crack Analysis:

Overall Average Score (out of 10): 5.2

- Frontwall Wall: 5.5/10
- Backwall Wall: 0.0/10
- Leftwall Wall: 10.0/10
- Rightwall Wall: 5.5/10

Severity Level: Medium

Recommendation: Monitor the structure and consider a professional inspection.