## **Building Health Inspection Report**

## Frontwall Wall



Backwall Wall



## **Leftwall Wall**



Rightwall Wall



Al-Based Risk Analysis

Al-Based Structural Crack Analysis:

Overall Average Score (out of 10): 7.0

- Frontwall Wall: 8.5/10

- Backwall Wall: 5.5/10

- Leftwall Wall: 5.5/10

- Rightwall Wall: 8.5/10

Severity Level: Low

Recommendation: Structure is likely healthy. No immediate action needed.